


HARBOR DRIVE


MASTER LIST OF STRUCTURES SURVEYED

Building #	Folio	Yr Built (GIS)	Yr Built (2008)	Yr Built (Permit)	Status	FMSF	Address				Current Name	Historic Name	Architect	Style
1	504212240100	1954			Non-Contributing	BD04496	3001	Harb	or I	Drive	Bahia Cabana		Paul M. Bradley	Mid-Century Modern
2	504212240090	1955	1953		Contributing		3007	Harb	or l	Drive	Bahia Cabana	Bahia Cabana	Platt Johnson	Modern Vernacular
3	504212NS0030	1958	1956		Contributing	BD04497	3013	Harb	or l	Drive	Mar Vista	Mar Vista Club	Gerard Pitt	Modern Vernacular
4	504212240070	1956	1951		Contributing		3019	Harb	or I	Drive			Theodore A. Meyer	Modern Vernacular
5	504212NR0060	1957	1955		Contributing	BD04498	3025	Harb	or l	Drive	Villa Madrid	Villa Madrid	Gerard Pitt	Mid-Century Modern
6	504212NT0160	1957	1953		Contributing		3037	Harb	or l	Drive	Bahia Vista	Bahia Vista Apartment	Robert E. Hansen	Modern Vernacular
7	504212NU0080	1957	1956		Contributing		3043	Harb	or l	Drive	Balboa Club	Balboa Club	Lester Avery	Modern Vernacular
8	504212240030	1951	1951		Non-Contributing		3049	Harb	or l	Drive	Southeast House		Little + Crawford	No Style
9	504212CH0120	1998	c2006		Non-Contributing		3055	Harb	or l	Drive	Harbourage Place			No Style
10A	504212NV0030	1957	1953		Contributing	BD04499	3073	Harb	or l	Drive	Harbor Club	Harbor Club Co-op	Morton Ironmonger	Modern Vernacular
10B	504212NV0030	1957	1953		Contributing	BD04499	3073	Harb	or l	Drive	Harbor Club	Harbor Club Co-op	Morton Ironmonger	Modern Vernacular
11	504212240170	1951	1950		Non-Contributing		3086	Harb	or l	Drive	Blarney Hotel		Gamble, Pownall & Gilroy	Modern Vernacular
12	504212240160	1950	1950		Non-Contributing	BD05250	1147	Seab	reeze	Blvd	Harbor Beach Inn	Harbor Beach Inn	Lester Avery	Modern Vernacular
13	504212240180	1951	1951		Contributing		3081	Harb	or l	Drive	Sea Beach Plaza		Courtney Stewart	Modern Vernacular
14A	504212240190	1958	1957		Contributing		3054	Harb	or l	Drive			Lester Avery	Modern Vernacular
14A	504212240190	1958	1957		Contributing		3054	Harb	or l	Drive			Lester Avery	Modern Vernacular
15	504212240200	1953	1952		Contributing		3048	Harb	or l	Drive		Motel Oceana Harbor	J. Richard Ogden Jr	Modern Vernacular
16	504212240210	1966	1964		Non-Contributing		3030	Harb	or I	Drive	Bahia Beach Resort		C. Edward Keiler	No Style
17	504212240240	1953	1952		Contributing		3012	Harb	or I	Drive	Bahia Cabana	Bahia Cabana	Lester Avery	Modern Vernacular
18	504212240220	1953	1953		Contributing		3018	Harb	or l	Drive	Bahia Cabana	Days Inn	Gamble, Pownall & Gilroy	Modern Vernacular











Building Number: 1 Address: 3001 Harbor Drive

Date: 1954 Architect: Paul M. Bradley Architectural Style: Mid-Century Modern Folio: 504212240100 Current Business Name (if applicable) Bahia Cabana

Contributing or Non-Contributing: Non-Contributing Existing Condition of Structure: Fair Noticeable Alterations: Yes If yes, what are the alterations? Alterations to exterior wall materials and fenestration Has building been demolished since 2008 survey? No

Number of Stories: 2 Number of Residential Living Units: N/A Number of Commercial Tenant Spaces: 1 Number of Hotel Rooms: 22 Building Use

- Restaurant
- Motel/Hotel

Building Materials

- Slumped Brick
- Aluminum
- Stucco
- Wood

Building Configuration: Irregular Building Design Features

- Awning at Entrance
- Boxed Window/Extruded Frame
- Railings (Non-Decorative)

Sign Types

- Awning Sign
- Wall Sign (Non-Illuminated)

Site Features

- Driveway (single or stacked)
- No Sidewalk
- Parking in Front
- Street Lighting

Roof Type: Flat

Roof Material: Flat Roof - Not Visible Window Type

- Fixed
- Single-Hung

With or Without Muntins: Without Muntins

Comments:

A full narrative is available in the Florida Master Site File form under file #BD04496

Geopoint Lat: 26.11 Lon: -80.106 Location Map



Reference Photo



Historic Photo



Building Number: 2 Address: 3007 Harbor Drive

Date: 1955 Architect: Platt Johnson Architectural Style: Modern Vernacular Folio: 504212240090 Current Business Name (if applicable) Bahia Cabana Beach Resort Contributing or Non-Contributing: Unsure Existing Condition of Structure: Fair Noticeable Alterations: Unsure Has building been demolished since 2008 survey? No

Number of Stories: 2 Number of Residential Living Units: N/A Number of Commercial Tenant Spaces: N/A Number of Hotel Rooms: 15 Building Use: Motel/Hotel

Building Materials

- Stucco
- Wood

Building Configuration: L-Shaped Building Design Features

- Balcony(ies)
- Catwalks (Exterior Corridors)
- Railings (Non-Decorative)

Sign Types

No Sign

Site Features

- Driveway (single or stacked)
- Hedge in front of structure
- No Sidewalk
- Parking in Front

Roof Type: Flat Roof Material: Flat Roof - Not Visible

Window Type: Fixed With or Without Muntins: Without Muntins

Geopoint

Lat: 26.11 Lon: -80.107

Location Map





Historic Photo None Available

Building Number: 3 Address: 3013 Harbor Drive

Date: 1958 Architect: Gerard Pitt Architectural Style: Modern Vernacular Folio: 504212NS0030 Current Business Name (if applicable) Mar Vista

Contributing or Non-Contributing: Contributing Existing Condition of Structure: Good Noticeable Alterations: Yes If yes, what are the alterations? Jalousie windows replaced with sliding Has building been demolished since 2008 survey? No

Number of Stories: 3 Number of Residential Living Units: 10 Number of Commercial Tenant Spaces: N/A Number of Hotel Rooms: N/A Building Use: Apartment/Condo

Building Materials: Stucco Building Configuration: Rectangular/Square Building Design Features

- Cantilevered Projection/Canopy
- Catwalks (Exterior Corridors)
- Railings (Non-Decorative)
- Floating Staircase

Sign Types

• Wall Sign (Non-Illuminated)

Site Features

- Driveway (single or stacked)
- Fence or Gate in front of structure
- No Sidewalk
- Parking in Front
- Wall in front of structure

Roof Type: Flat Roof Material: Flat Roof - Not Visible

Window Type

- Jalousie
- Sliders

With or Without Muntins: Without Muntins

Comments:

A full narrative is available in the Florida Master Site File form under file #BD04497

Geopoint

Lat: 26.11 Lon: -80.107

Location Map





Historic Photo None Available

Building Number: 4 Address: 3019 Harbor Drive

Date: 1956 Architect: Theodore A. Meyer Architectural Style: Modern Vernacular Folio: 504212240070 Current Business Name (if applicable) n/a

Contributing or Non-Contributing: Contributing Existing Condition of Structure: Fair Noticeable Alterations: Yes If yes, what are the alterations? Removal of balcony railings Has building been demolished since 2008 survey? No

Number of Stories: 2 Number of Residential Living Units: 14 Number of Commercial Tenant Spaces: N/A Number of Hotel Rooms: N/A Building Use: Apartment/Condo

Building Materials

- Roman Brick
- Stucco

Building Configuration: L-Shaped Building Design Features

- Boxed Window/Extruded Frame
- Catwalks (Exterior Corridors)
- Eyebrows
- Railings (Non-Decorative)

Sign Types

No Sign

Site Features

- Driveway (single or stacked)
- Fence or Gate in front of structure
- No Sidewalk
- Parking in Front

Roof Type: Flat Roof Material: Flat Roof - Not Visible

Window Type

- Fixed
- Single-Hung
- Sliders

With or Without Muntins: Without Muntins

Geopoint

Lat: 26.11 Lon: -80.108

Location Map



Reference Photo



Historic Photo



Building Number: 5A Address: 3025 Harbor Drive

Date: 1957 Architect: Gerard Pitt Architectural Style: Mid-Century Modern Folio: 504212NR0060 Current Business Name (if applicable) Villa Madrid

Contributing or Non-Contributing: Contributing Existing Condition of Structure: Good Noticeable Alterations: Yes If yes, what are the alterations? Select windows have been replaced. Has building been demolished since 2008 survey? No

Number of Stories: 2 Number of Residential Living Units: 4 Number of Commercial Tenant Spaces: N/A Number of Hotel Rooms: N/A Building Use: Apartment/Condo

Building Materials: Stucco Building Configuration: Rectangular/Square Building Design Features

- Boxed Window/Extruded Frame
- Built-in Planters
- Railings (Non-Decorative)

Sign Types

Monument Sign

Site Features

- Driveway (single or stacked)
- Fence or Gate in front of structure
- No Sidewalk
- Street Lighting
- Trash can

Roof Type: Flat Roof Material: Flat Roof - Not Visible Window Type

- Awning
- Fixed
- Jalousie
- Single-Hung
- Sliders

With or Without Muntins: Without Muntins

Comments

Front right unit

A full narrative is available in the Florida Master Site File form under file #BD04498

Geopoint

Lat: 26.11 Lon: -80.108

Location Map





Historic Photo None Available

Building Number: 5B Address: 3025 Harbor Drive

Date: 1957 Architect: Gerard Pitt Architectural Style: Mid-Century Modern Folio: 504212NR0060 Current Business Name (if applicable) Villa Madrid

Contributing or Non-Contributing: Contributing Existing Condition of Structure: Good Noticeable Alterations: Yes If yes, what are the alterations? windows replaced Has building been demolished since 2008 survey? No

Number of Stories: 2 Number of Residential Living Units: 4 Number of Commercial Tenant Spaces: N/A Number of Hotel Rooms: N/A Building Use: Apartment/Condo

Building Materials: Stucco Building Configuration: Rectangular/Square Building Design Features

- Boxed Window/Extruded Frame
- Built-in Planters
- Railings (Non-Decorative)

Sign Types

Monument Sign

Site Features

- Driveway (single or stacked)
- Fence or Gate in front of structure
- No Sidewalk
- Street Lighting
- Trash can

Roof Type: Flat

Roof Material: Flat Roof - Not Visible Window Type

- Awning
- Fixed
- Jalousie
- Single-Hung
- Sliders

With or Without Muntins: Without Muntins

Comments

Front middle unit

A full narrative is available in the Florida Master Site File form under file #BD04498

Geopoint

Lat: 26.11 Lon: -80.108

Location Map





Historic Photo None Available

Building Number: 5C Address: 3025 Harbor Drive

Date: 1957 Architect: Gerard Pitt Architectural Style: Mid-Century Modern Folio: 504212NR0060 Current Business Name (if applicable) Villa Madrid

Contributing or Non-Contributing: Contributing Existing Condition of Structure: Good Noticeable Alterations: Yes If yes, what are the alterations? windows replaced Has building been demolished since 2008 survey? No

Number of Stories: 2 Number of Residential Living Units: 4 Number of Commercial Tenant Spaces: N/A Number of Hotel Rooms: N/A Building Use: Apartment/Condo

Building Materials: Stucco Building Configuration: Rectangular/Square Architectural Style: Mid-Century Modern Building Design Features

- Boxed Window/Extruded Frame
- Built-in Planters
- Railings (Non-Decorative)

Sign Types

Monument Sign

Site Features

- Driveway (single or stacked)
- Fence or Gate in front of structure
- No Sidewalk
- Street Lighting
- Trash can

Roof Type: Flat Roof Material: Flat Roof - Not Visible Window Type

- Awning
- Fixed
- Jalousie
- Single-Hung
- Sliders

With or Without Muntins: Without Muntins

Comments

Front left unit

A full narrative is available in the Florida Master Site File form under file #BD04498

Geopoint

Lat: 26.11 Lon: -80.108

Location Map





Historic Photo None Available

Building Number: 5D Address: 3025 Harbor Drive

Date: 1957 Architect: Gerard Pitt Architectural Style: Mid-Century Modern Folio: 504212NR0060 Current Business Name (if applicable) Villa Madrid

Contributing or Non-Contributing: Contributing Existing Condition of Structure: Good Noticeable Alterations: Yes If yes, what are the alterations? windows replaced Has building been demolished since 2008 survey? No

Number of Stories: 2 Number of Residential Living Units: 4 Number of Commercial Tenant Spaces: N/A Number of Hotel Rooms: N/A Building Use: Apartment/Condo

Building Materials: Stucco Building Configuration: Rectangular/Square Architectural Style: Mid-Century Modern Building Design Features

- Boxed Window/Extruded Frame
- Built-in Planters
- Railings (Non-Decorative)

Sign Types

Monument Sign

Site Features

- Driveway (single or stacked)
- Fence or Gate in front of structure
- No Sidewalk
- Street Lighting
- Trash can
- Roof Type: Flat

Roof Material: Flat Roof - Not Visible Window Type

- Awning
- Fixed
- Jalousie
- Single-Hung
- Sliders

With or Without Muntins: Without Muntins

Comments

Rear left unit

A full narrative is available in the Florida Master Site File form under file #BD04498

Geopoint

Lat: 26.11 Lon: -80.108

Location Map



Reference Photo



Building Number: 5E Address: 3025 Harbor Drive

Date: 1957 Architect: Gerard Pitt Architectural Style: Mid-Century Modern Folio: 504212NR0060 Current Business Name (if applicable) Villa Madrid

Contributing or Non-Contributing: Contributing Existing Condition of Structure: Good Noticeable Alterations: Yes If yes, what are the alterations? windows replaced Has building been demolished since 2008 survey? No

Number of Stories: 2 Number of Residential Living Units: 4 Number of Commercial Tenant Spaces: N/A Number of Hotel Rooms: N/A Building Use: Apartment/Condo

Building Materials: Stucco Building Configuration: Rectangular/Square Architectural Style: Mid-Century Modern Building Design Features

- Boxed Window/Extruded Frame
- Built-in Planters
- Railings (Non-Decorative)

Sign Types

Monument Sign

Site Features

- Driveway (single or stacked)
- Fence or Gate in front of structure
- No Sidewalk
- Street Lighting
- Trash can

Roof Type: Flat Roof Material: Flat Roof - Not Visible Window Type

- Awning
- Fixed
- Jalousie
- Single-Hung
- Sliders

With or Without Muntins: Without Muntins

Comments

Rear middle unit

A full narrative is available in the Florida Master Site File form under file #BD04498

Geopoint

Lat: 26.11 Lon: -80.108

Location Map



Reference Photo



Historic Photo

None Available

City of Fort Lauderdale

Building Number: 5F Address: 3025 Harbor Drive

Date: 1957 Architect: Gerard Pitt Architectural Style: Mid-Century Modern Folio: 504212NR0060 Current Business Name (if applicable) Villa Madrid

Contributing or Non-Contributing: Contributing Existing Condition of Structure: Good Noticeable Alterations: Yes If yes, what are the alterations? windows replaced Has building been demolished since 2008 survey? No

Number of Stories: 2 Number of Residential Living Units: 4 Number of Commercial Tenant Spaces: N/A Number of Hotel Rooms: N/A Building Use: Apartment/Condo

Building Materials: Stucco Building Configuration: Rectangular/Square Architectural Style: Mid-Century Modern Building Design Features

- Boxed Window/Extruded Frame
- Built-in Planters
- Railings (Non-Decorative)

Sign Types

Monument Sign

Site Features

- Driveway (single or stacked)
- Fence or Gate in front of structure
- No Sidewalk
- Street Lighting
- Trash can
- Roof Type: Flat

Roof Material: Flat Roof - Not Visible Window Type

- Awning
- Fixed
- Jalousie
- Single-Hung
- Sliders

With or Without Muntins: Without Muntins

Comments

Rear right unit

A full narrative is available in the Florida Master Site File form under file #BD04498

Geopoint

Lat: 26.11 Lon: -80.108

Location Map





Historic Photo None Available

Building Number: 6 Address: 3037 Harbor Drive

Date: 1957 Architect: Robert E. Hansen Architectural Style: Modern Vernacular Folio: 504212NT0160 Current Business Name (if applicable) Bahia Vista

Contributing or Non-Contributing: Contributing Existing Condition of Structure: Good Noticeable Alterations: Unsure If yes, what are the alterations? Change of balcony railings; parking canopies in front of structure Has building been demolished since 2008 survey? No Number of Stories: 2 Number of Residential Living Units: 19 Number of Commercial Tenant Spaces: N/A Number of Hotel Rooms: N/A Building Use: Apartment/Condo

Building Materials

- Concrete
- Slumped Brick
- Stucco
- Wood

Building Configuration: L-Shaped Building Design Features

- Beanpoles
- Boxed Window/Extruded Frame
- Built-in Planters
- Catwalks (Exterior Corridors)
- Railings (Non-Decorative)

Sign Types

• Wall Sign (Non-Illuminated)

Site Features

- Driveway (single or stacked)
- Fence or Gate in front of structure
- Hedge in front of structure
- No Sidewalk
- Parking in Front

Roof Type: Flat Roof Material: Fla

Roof Material: Flat Roof - Not Visible Window Type

- Awning
- Fixed

With or Without Muntins: Not Applicable

Comments Fire hydrant

Geopoint

Lat: 26.11 Lon: -80.109

Location Map



Reference Photo



Building Number: 7A Address: 3043 Harbor Drive

Date: 1957 Architect: Lester Avery Architectural Style: Modern Vernacular Folio: 504212NU0080 Current Business Name (if applicable) Balboa Club

Contributing or Non-Contributing: Contributing Existing Condition of Structure: Good Noticeable Alterations: Unsure Has building been demolished since 2008 survey? No

Number of Stories: 2 Number of Residential Living Units: 4 Number of Commercial Tenant Spaces: n/a Number of Hotel Rooms: n/a Building Use: Apartment/Condo

Building Materials: Stucco Building Configuration: Rectangular/Square Building Design Features

- Railings (Non-Decorative)
- Sign Types
 - Wall Sign (Non-Illuminated)

Site Features

- Driveway (single or stacked)
- No Sidewalk
- Parking in Front

Roof Type: Hip Roof Material: Flat Tile

Window Type

- Awning
- Fixed
- Jalousie
- Single-Hung

With or Without Muntins: Without Muntins

Geopoint

Lat: 26.11 Lon: -80.109

Location Map





Historic Photo None Available

Building Number: 7B Address: 3043 Harbor Drive

Date: 1957 Architect: Lester Avery Architectural Style: Modern Vernacular Folio: 504212NU0080 Current Business Name (if applicable) Balboa Club

Contributing or Non-Contributing: Contributing Existing Condition of Structure: Good Noticeable Alterations: Yes If yes, what are the alterations? Change of stair/balcony railings Has building been demolished since 2008 survey? No

Number of Stories: 1 Number of Residential Living Units: 4 Number of Commercial Tenant Spaces: N/A Number of Hotel Rooms: N/A Building Use: Apartment/Condo

Building Materials: Stucco Building Configuration: Rectangular/Square Building Design Features: Railings (Non-Decorative) Sign Types: Wall Sign (Non-Illuminated) Site Features

- Driveway (single or stacked)
- No Sidewalk
- Parking in Front

Roof Type: Hip Roof Material: Flat Tile

Window Type

- Awning
- Fixed
- Jalousie
- Single-Hung

With or Without Muntins: Without Muntins

Geopoint

Lat: 26.11 Lon: -80.108

Location Map



Reference Photo



Historic Photo

None Available

Building Number: 7C Address: 3043 Harbor Drive

Date: 1957 Architect: Lester Avery Architectural Style: Modern Vernacular Folio: 504212NU0080 Current Business Name (if applicable) Balboa Club

Contributing or Non-Contributing: Contributing Existing Condition of Structure: Good Noticeable Alterations: Unsure Has building been demolished since 2008 survey? No

Number of Stories: 2 Number of Residential Living Units: 2 Number of Commercial Tenant Spaces: N/A Number of Hotel Rooms: N/A Building Use: Apartment/Condo

Building Materials: Stucco Building Configuration: Rectangular/Square Building Design Features

- Railings (Non-Decorative)
- Sign Types
 - Wall Sign (Non-Illuminated)

Site Features

- Driveway (single or stacked)
- No Sidewalk
- Parking in Front

Roof Type: Hip Roof Material: Flat Tile

Window Type

- Awning
- Fixed
- Jalousie
- Single-Hung

With or Without Muntins: Without Muntins

Geopoint

Lat: 26.11 Lon: -80.109

Location Map



Reference Photo



Building Number: 7D Address: 3043 Harbor Drive

Date: 1957 Architect: Lester Avery Architectural Style: Modern Vernacular Folio: 504212NU0080 Current Business Name (if applicable) Balboa Club

Contributing or Non-Contributing: Contributing Existing Condition of Structure: Good Noticeable Alterations: Yes If yes, what are the alterations? Change of stair/balcony railings Has building been demolished since 2008 survey? No

Number of Stories: 2 Number of Residential Living Units: 4 Number of Commercial Tenant Spaces: N/A Number of Hotel Rooms: N/A Building Use: Apartment/Condo

Building Materials: Stucco Building Configuration: Rectangular/Square Building Design Features

• Railings (Non-Decorative)

Sign Types

• Wall Sign (Non-Illuminated)

Site Features

- Driveway (single or stacked)
- No Sidewalk
- Parking in Front

Roof Type: Hip Roof Material: Flat Tile

Window Type

- Awning
- Fixed
- Jalousie
- Single-Hung

With or Without Muntins: Without Muntins

Geopoint

Lat: 26.11 Lon: -80.109

Location Map





Historic Photo None Available

Building Number: 8A Address: 3049 Harbor Drive

Date: 1951 Architect: Little + Crawford Architectural Style: No Style Folio: 504212240030 Current Business Name (if applicable) Southeast House

Contributing or Non-Contributing: Non-Contributing Existing Condition of Structure: Excellent Noticeable Alterations: Yes If yes, what are the alterations? Appears to have removed original materials/detailing during renovation work Has building been demolished since 2008 survey? No

Number of Stories: 2 Number of Residential Living Units: 4 Number of Commercial Tenant Spaces: N/A Number of Hotel Rooms: N/A Building Use: Apartment/Condo

Building Materials: Stucco Building Configuration: Rectangular/Square Building Design Features

- Eyebrows
- Balcony(ies)
- Railings (Decorative)

Sign Types

No Sign

Site Features

- Driveway (single or stacked)
- Fence or Gate in front of structure
- No Sidewalk
- Parking in Front
- Wall in front of structure

Roof Type: Hip Roof Material: Barrel or Spanish Tile Window Type

- Casement
- Fixed
- Sliders

With or Without Muntins: Without Muntins

Comments

Bulb out for entry sidewalk between parking spaces

Geopoint

Lat: 26.11 Lon: -80.108

Location Map



Reference Photo



Building Number: 8B Address: 3049 Harbor Drive

Date: 1951 Architect: Little + Crawford Architectural Style: No Style Folio: 504212240030 Current Business Name (if applicable) Southeast House

Contributing or Non-Contributing: Non-Contributing Existing Condition of Structure: Excellent Noticeable Alterations: Unsure If yes, what are the alterations? Appears to have removed original materials/detailing Has building been demolished since 2008 survey? No

Number of Stories: 2 Number of Residential Living Units: 4 Number of Commercial Tenant Spaces: n/a Number of Hotel Rooms: n/a Building Use: Apartment/Condo

Building Materials: Stucco Building Configuration: Rectangular/Square Building Design Features

- Eyebrows
- Balcony(ies)
- Railings (Decorative)

Sign Types

No Sign

Site Features

- Driveway (single or stacked)
- Fence or Gate in front of structure
- No Sidewalk
- Parking in Front
- Wall in front of structure

Roof Type: Hip Roof Material: Barrel or Spanish Tile

Window Type

- Casement
- Fixed
- Sliders

With or Without Muntins: Without Muntins

Geopoint

Lat: 26.11 Lon: -80.109

Location Map



Reference Photo



Historic Photo



Building Number: 9 Address: 3055 Harbor Drive

Date: 1998 Architect: unknown Architectural Style: No Style Folio: 504212CH0120 Current Business Name (if applicable) Harbourage Place

Contributing or Non-Contributing: Non-Contributing Existing Condition of Structure: Excellent Noticeable Alterations: No Has building been demolished since 2008 survey? No

Number of Stories: 20 Number of Commercial Tenant Spaces: N/A Number of Hotel Rooms: N/A Building Use: Apartment/Condo

Building Materials: Stucco Building Configuration: Rectangular/Square Building Design Features

- Balcony(ies)
- Porte Cochere
- Other

Sign Types

Monument Sign

Site Features

- Driveway (single or stacked)
- No Sidewalk

Roof Type

- Flat
- Gable

Roof Material: Flat Roof - Not Visible

Window Type

• Fixed

With or Without Muntins: Without Muntins

Geopoint

Lat: 26.109 Lon: -80.109

Location Map





Historic Photo None Available

Building Number: 10A Address: 3073 Harbor Drive

Date: 1957 Architect: Morton Ironmonger Architectural Style: Modern Vernacular Folio: 504212NV0030 Current Business Name (if applicable) Harbor Club

Contributing or Non-Contributing: Contributing Existing Condition of Structure: Good Noticeable Alterations: Yes If yes, what are the alterations? Awning windows replaced Has building been demolished since 2008 survey? No

Number of Stories: 3 Number of Residential Living Units: Unknown Number of Commercial Tenant Spaces: N/A Number of Hotel Rooms: N/A Building Use: Apartment/Condo

Building Materials: Stucco Building Configuration: irregular Building Design Features

- Balcony(ies)
- Beanpoles
- Catwalks (Exterior Corridors)
- Floating Staircase
- Marine Imagery
- Railings (Decorative)
- Railings (Non-Decorative)
- Woggles
- Other

Sign Types

Pole Sign

Site Features

- Driveway (single or stacked)
- Fence or Gate in front of structure
- No Sidewalk
- Parking in Front
- Other

Roof Type: Flat

Roof Material: Flat Roof - Not Visible Window Type

- Fixed
- Single-Hung

With or Without Muntins: Without Muntins

Comments:

A full narrative is available in the Florida Master Site File form under file #BD04499

Geopoint

Lat: 26.109 Lon: -80.109

Location Map



Reference Photo



Historic Photo

None Available

Building Number: 10B Address: 3073 Harbor Drive

Date: 1957 Architect: Morton Ironmonger Architectural Style: Modern Vernacular Folio: 504212NV0030 Current Business Name (if applicable) Harbor Club

Contributing or Non-Contributing: Contributing Existing Condition of Structure: Good Noticeable Alterations: Yes If yes, what are the alterations? Awning windows replaced Has building been demolished since 2008 survey? No

Number of Stories: 3 Number of Residential Living Units: Unknown Number of Commercial Tenant Spaces: N/A Number of Hotel Rooms: N/A Building Use: Apartment/Condo

Building Materials: Stucco Building Configuration: Irregular Building Design Features

- Balcony(ies)
- Beanpoles
- Catwalks (Exterior Corridors)
- Floating Staircase
- Marine Imagery
- Railings (Decorative)
- Railings (Non-Decorative)
- Woggles
- Other

Sign Types

Pole Sign

Site Features

- Driveway (single or stacked)
- Fence or Gate in front of structure
- No Sidewalk
- Parking in Front
- Other

Roof Type: Flat

Roof Material: Flat Roof - Not Visible Window Type

- Fixed
- Single-Hung

With or Without Muntins: Without Muntins

Comments:

A full narrative is available in the Florida Master Site File form under file #BD04499

Geopoint

Lat: 26.108 Lon: -80.108

Location Map





Historic Photo None Available

Building Number: 11 Address: 3086 Harbor Drive

Date: 1951 Architect: Gamble, Pownall & Gilroy Architectural Style: Modern Vernacular Folio: 504212240170 Current Business Name (if applicable) Blarney Hotel

Contributing or Non-Contributing: Non-Contributing Existing Condition of Structure: Fair Noticeable Alterations: Yes, addition to rear and alterations to front façade. Has building been demolished since 2008 survey? No

Number of Stories: 3 Number of Residential Living Units: N/A Number of Commercial Tenant Spaces: N/A Number of Hotel Rooms: 20 Building Use: Motel/Hotel

Building Materials

- Brick
- Mosaic Tile
- Stucco
- Other

Building Configuration: Courtyard/U-Shaped Building Design Features

- Balcony(ies)
- Catwalks (Exterior Corridors)
- Railings (Decorative)
- Other

Sign Types

- Hanging Sign
- Wall Sign (Illuminated)

Site Features

- Driveway (single or stacked)
- Fence or Gate in front of structure
- No Sidewalk
- Parking in Front

Roof Type: Flat Roof Material: Flat Roof - Not Visible

Window Type

- Fixed
- Jalousie
- Single-Hung
- Storefront Windows

With or Without Muntins: Without Muntins

Geopoint

Lat: 26.108 Lon: -80.108 Location Map



Reference Photo







June/July 2017

Building Number: 12 Address: 1147 Seabreeze Blvd

Date: 1950 Architect: Lester Avery Architectural Style: Modern Vernacular Folio: 504212240160 Current Business Name (if applicable) Harbor Beach Inn

Contributing or Non-Contributing: Non-Contributing Existing Condition of Structure: Good Noticeable Alterations: Unsure Has building been demolished since 2008 survey? No

Number of Stories: 2 Number of Residential Living Units: N/A Number of Commercial Tenant Spaces: N/A Number of Hotel Rooms: 15 Building Use: Apartment/Condo

Building Materials

- Štucco
- Other

Building Configuration: Courtyard/U-Shaped Building Design Features

- Awning at Entrance
- Balcony(ies)
- Catwalks (Exterior Corridors)
- Railings (Decorative)

Sign Types

Monument Sign

Site Features

- Driveway (single or stacked)
- Fence or Gate in front of structure
- Hedge in front of structure
- No Sidewalk
- Swale between street and sidewalk
- Wall in front of structure

Roof Type: Flat Roof Material: Flat Roof - Not Visible

Window Type

- Awning
- Fixed
- Jalousie

With or Without Muntins: Without Muntins

Comments:

A full narrative is available in the Florida Master Site File form under file #BD05250.

Geopoint

Lat: 26.108 Lon: -80.108

Location Map





Historic Photo None Available

Building Number: 13 Address: 3081 Harbor Drive

Date: 1951 Architect: Courtney Stewart Architectural Style: Modern Vernacular Folio: 504212240180 Current Business Name (if applicable) Sea Beach Plaza

Contributing or Non-Contributing: Contributing Existing Condition of Structure: Good Noticeable Alterations: Yes If yes, what are the alterations? Removal of stucco art Has building been demolished since 2008 survey? No

Number of Stories: 3 Number of Residential Living Units: N/A Number of Commercial Tenant Spaces: N/A Number of Hotel Rooms: 40 Building Use: Motel/Hotel

Building Materials: Stucco Building Configuration: Courtyard/U-Shaped Building Design Features

Railings (Non-Decorative)

Sign Types

Pole Sign

Site Features

- Driveway (single or stacked)
- Fence or Gate in front of structure
- No Sidewalk
- Parking in Front

Roof Type: Flat Roof Material: Flat Roof - Not Visible

Window Type

- Awning
- Fixed
- Single-Hung

With or Without Muntins: With Muntins

Geopoint

Lat: 26.109 Lon: -80.108

Location Map





Historic Photo None Available

Building Number: 14A Address: 3054 Harbor Drive

Date: 1958 Architect: Lester Avery Architectural Style: Modern Vernacular Folio: 504212240190 Current Business Name (if applicable) n/a

Contributing or Non-Contributing: Non-Contributing Existing Condition of Structure: Fair Noticeable Alterations: Unsure Has building been demolished since 2008 survey? No

Number of Stories: 2 Number of Residential Living Units: 0 Number of Commercial Tenant Spaces: 0 Number of Hotel Rooms: 0 Building Use: Other – Vacant

Building Materials: Stucco Building Configuration: Rectangular/Square Building Design Features

- Brise-Soleils
- Railings (Non-Decorative)
- Catwalks (Exterior Corridors)
- Beanpoles
- Screen Block/Breeze Block

Sign Types

No Sign

Site Features

- Driveway (single or stacked)
- Fence or Gate in front of structure
- Parking in Front
- Hedge in front of structure

Roof Type: Flat Roof Material: Flat Roof - Not Visible

Window Type

- Awning
- Fixed
- Jalousie

With or Without Muntins: Without Muntins

Comments

Vacant. Development Review Committee (DRC) approved project for this parcel.

Geopoint

Lat: 26.109 Lon: -80.108

Location Map



Reference Photo



Building Number: 14B Address: 3054 Harbor Drive

Date: 1958 Architect: Lester Avery Architectural Style: Modern Vernacular Folio: 504212240190 Current Business Name (if applicable) n/a

Contributing or Non-Contributing: Non-Contributing Existing Condition of Structure: Fair Noticeable Alterations: Unsure Has building been demolished since 2008 survey? No

Number of Stories: 2 Number of Residential Living Units: 0 Number of Commercial Tenant Spaces: 0 Number of Hotel Rooms: 0 Building Use: Other – Vacant

Building Materials: Stucco Building Configuration: Rectangular/Square Building Design Features

- Brise-Soleils
- Railings (Non-Decorative)
- Catwalks (Exterior Corridors)
- Screen Block/Breeze Block

Sign Types

No Sign

Site Features

- Driveway (single or stacked)
- Fence or Gate in front of structure
- Parking in Front
- Hedge in front of structure

Roof Type: Flat Roof Material: Flat Roof - Not Visible

Window Type

- Awning
- Fixed
- Jalousie

With or Without Muntins: Without Muntins

Comments

Vacant. Development Review Committee (DRC) approved project for this parcel.

Geopoint

Lat: 26.109 Lon: -80.108

Location Map



Reference Photo



Building Number: 15 Address: 3048 Harbor Drive

Date: 1953 Architect: J. Richard Ogden Jr Architectural Style: Modern Vernacular Folio: 504212240200 Current Business Name (if applicable) n/a

Contributing or Non-Contributing: Non-Contributing Existing Condition of Structure: Fair Noticeable Alterations: Yes If yes, what are the alterations? pool drained/filled, removal of marine decor Has building been demolished since 2008 survey? No

Number of Stories: 2 Number of Residential Living Units: 0 Number of Commercial Tenant Spaces: 0 Number of Hotel Rooms: 0 Building Use: Other - Vacant

Building Materials

- Roman Brick
- Stucco

Building Configuration: Courtyard/U-Shaped Building Design Features

- Beanpoles
- Catwalks (Exterior Corridors)
- Railings (Non-Decorative)

Sign Types

No Sign

Site Features

- Driveway (single or stacked)
- Fence or Gate in front of structure
- No Sidewalk
- Parking in Front
- Other

Roof Type: Flat Roof Material: Flat Roof - Not Visible

Window Type

- Awning
- Single-Hung

With or Without Muntins: Without Muntins

Comments

Vacant for 20 years, slated for demolition

Geopoint

Lat: 26.11 Lon: -80.108

Location Map





Historic Photo None Available

Building Number: 16 Address: 3030 Harbor Drive

Date: 1966 Architect: C. Edward Keiler Architectural Style: No Style Folio: 504212240210 Current Business Name (if applicable) Bahia Beach Resort

Contributing or Non-Contributing: Non-Contributing Existing Condition of Structure: Good Noticeable Alterations: Yes If yes, what are the alterations? Railings replaced Has building been demolished since 2008 survey? No

Number of Stories: 6 Number of Residential Living Units: N/A Number of Commercial Tenant Spaces: N/A Number of Hotel Rooms: 35 Building Use: Motel/Hotel

Building Materials

- Stucco
- Other scored concrete

Building Configuration: Rectangular/Square Building Design Features

- Cantilevered Projection/Canopy
- Catwalks (Exterior Corridors)
- Railings (Non-Decorative)

Sign Types

Pole Sign

Site Features

- Driveway (single or stacked)
- Parking in Front

Roof Type: Flat Roof Material: Flat Roof - Not Visible

Window Type

- Single-Hung
- Fixed

With or Without Muntins: Without Muntins

Geopoint

Lat: 26.11 Lon: -80.108

Location Map





Historic Photo None Available

Building Number: 17 Address: 3018 Harbor Drive

Date: 1953 Architect: Gamble, Pownall & Gilroy Architectural Style: Modern Vernacular Folio: 504212240220 Current Business Name (if applicable) Bahia Cabana

Contributing or Non-Contributing: Contributing Existing Condition of Structure: Good Noticeable Alterations: Unsure Has building been demolished since 2008 survey? No

Number of Stories: 2 Number of Residential Living Units: N/A Number of Commercial Tenant Spaces: N/A Number of Hotel Rooms: 13 Building Use: Motel/Hotel

Building Materials

Stucco

Building Configuration: Rectangular/Square Building Design Features

- Boxed Window/Extruded Frame
- Cantilevered Projection/Canopy
- Eyebrows
- Marine Imagery
- Railings (Non-Decorative)

Sign Types

No Sign

Site Features

- Driveway (single or stacked)
- Dumpster in front of structure
- No Sidewalk
- Parking in Front

Roof Type: Flat Roof Material: Flat Roof - Not Visible

Window Type

- Awning
- Fixed

With or Without Muntins: Without Muntins

Geopoint

Lat: 26.11 Lon: -80.108

Location Map





Historic Photo None Available

Building Number: 18 Address: 3012 Harbor Drive

Date: 1953 Architect: Lester Avery Architectural Style: Modern Vernacular Folio: 504212240240 Current Business Name (if applicable) Bahia Cabana Beach Resort

Contributing or Non-Contributing: Contributing Existing Condition of Structure: Good Noticeable Alterations: Unsure Has building been demolished since 2008 survey? No

Number of Stories: 2 Number of Residential Living Units: N/A Number of Commercial Tenant Spaces: N/A Number of Hotel Rooms: 16 Building Use: Motel/Hotel

Building Materials: Stucco Building Design Features

- Balcony(ies)
- Beanpoles
- Catwalks (Exterior Corridors)
- Railings (Non-Decorative)
- Other

Sign Types

• Wall Sign (Non-Illuminated)

Site Features

- Driveway (single or stacked)
- Parking in Front

Roof Type: Flat Roof Material: Flat Roof - Not Visible

Window Type

- Awning
- Fixed

With or Without Muntins: Without Muntins

Geopoint

Lat: 26.11 Lon: -80.107

Location Map





Historic Photo None Available