

Site Number	Contributing or Non-Contributing	Architectural Style	Folio	Address	Year Built	Permit Year	# of Buildings	Flood Zone	Architect	Original Owner	Alterations
BD02056	Contributing	Mediterranean Revival	504215015601	314 SW 20 ST	1936	No permit record	2	0.2PCT	UNKNOWN	UNKNOWN	Replacement of select windows in 2004
BD02057	Contributing	Mediterranean Revival	504215015610	316 SW 20 ST #1-2	1939	No permit record	1	0.2PCT	UNKNOWN	UNKNOWN	None known
BD02058	Contributing	Mediterranean Revival	504215015620	322 SW 20 ST	1925	No permit record	2	0.2PCT	0.2PCT	UNKNOWN	Addition in 1963
BD02059	Contributing	Mediterranean Revival	504215015630	328 SW 20 ST	1925	No permit record	1	0.2PCT	UNKNOWN	UNKNOWN	Remodel in 2005
BD02060	Contributing	Mediterranean Revival	504215015640	330 SW 20 ST #1-3	c.1925	No Permit Record	1	0.2PCT	UNKNOWN	UNKNOWN	None known
BD02061	Contributing	Mediterranean Revival	504215015260	327 SW 20 ST #1-4	1960	No Permit Record	2	0.2PCT	UNKNOWN	UNKNOWN	Conversion of garage into apartment in 1946; Replacement windows and doors in 2013
BD02062	Contributing	Mediterranean Revival	504215015270	323 SW 20 ST	1925	No permit record	2	0.2PCT	UNKNOWN	UNKNOWN	Addition in 2018
BD02063	Contributing	Mediterranean Revival	504215015280	319 SW 20 ST	1925	No permit record	1	0.2PCT	UNKNOWN	UNKNOWN	Replacement windows and doors in 2019
BD02064	Contributing	Mediterranean Revival	504215015300	309 SW 20 ST #1-3	1939	No permit record	4	0.2PCT	UNKNOWN	UNKNOWN	Remodel moved building in 1944; One-story building in 1987; Replacement of select windows in 1992;
BD07756	Non-Contributing	No Style	504215015290	315 SW 20 ST	1946	1953	1	0.2PCT	VICTOR LARSON	ROMERO,ELENA V	None known
BD02055	Contributing	Mediterranean Revival	504215015591	304 SW 20 ST	c. 1925	No permit record	1	0.2PCT	UNKNOWN	UNKNOWN	None known