

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07011	504216220010	1500 SW 12th Street	Shady Banks	Contributing	1948	Transitional Ranch	William T Vaughn	Stucco and Brick	Flat	Membrane	Double/Single-Hung
BD07012	504216220020	1506 Davie Boulevard	Shady Banks	Contributing	1948	Transitional Ranch	William T Vaughn	Stucco	Side Gable	asphalt shingle	Double/Single-Hung
	504216220040	1514 Davie Boulevard	Shady Banks	Non-Contributing	2016	Neo-Mediterranean	Ruben Pajol	Stucco	Hipped	Terra-cotta barrel tile	Sliding
BD07405	504216220030	1510 SW 12th Street	Shady Banks	Non-Contributing	1948	Transitional Ranch	William T Vaughn	Stucco	Side Gable	Membrane	Awning
BD07013	504216220050	1518 Davie Boulevard	Shady Banks	Contributing	1948	Transitional Ranch	William T Vaughn	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07014	504216220060	1522 Davie Boulevard	Shady Banks	Contributing	1948	Transitional Ranch	William T Vaughn	Stucco and Brick	Flat	Membrane	Double/Single-Hung
BD07015	504216060010	1600 Davie Boulevard	Shady Banks	Contributing	1956	Transitional Ranch	Lester Avery	Stucco	Side Gable	Asphalt shingle	Sliding
BD07016	504216060020	1604 Davie Boulevard	Shady Banks	Contributing	1957	Transitional Ranch	Lester Avery	Stucco	Side Gable	Asphalt shingle	Double/Single-Hung
BD07017	504216060030	1616 Davie Boulevard	Shady Banks	Contributing	1952	Transitional Ranch	Wimer and McKirahan	Stucco	Hipped	Asphalt shingle	Sliding
BD07018	504216070100	1612 SW 12th Court	Shady Banks	Contributing	1951	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Double/Single-Hung
BD07019	504216070030	1613 SW 12th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07020	504216070040	1609 SW 12th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07021	504216070080	1604 SW 12th Court	Shady Banks	Non-Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Fixed
BD07022	504216070090	1608 SW 12th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07023	504216220180	1524 SW 12th Court	Shady Banks	Contributing	1950	Transitional Ranch	Unknown	Board and Batten	Shed	Membrane	Sliding
BD07406	504216220170	1518 SW 12th Court	Shady Banks	Non-Contributing	1948	Transitional Ranch	John B. O'Neill	Stucco	Hipped	Membrane	Casement
BD07024	504216070060	1601 SW 12th Court	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Unknown
BD07025	504216070050	1605 SW 12th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07407	504216220070	1521 SW 12th Court	Shady Banks	Non-Contributing	1948	Transitional Ranch	William T Vaughn	Stucco	Hipped	Barrel tile	Casement
BD07026	504216070070	1600 SW 12th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Casement
BD07027	504216220080	1517 SW 12th Court	Shady Banks	Contributing	1948	Transitional Ranch	William T Vaughn	Stucco	Hipped	Asphalt shingle	Double/Single-Hung
BD07028	504216220160	1514 SW 12th Court	Shady Banks	Contributing	1949	Transitional Ranch	Robert Jahelka	Stucco	Mix	Membrane	Double/Single-Hung
BD07029	504216220090	1513 SW 12th Court	Shady Banks	Contributing	1949	Transitional Ranch	William T Vaughn	Stucco	Front Gable	Flat tile	Double/Single-Hung
BD07030	504216220150	1510 SW 12th Court	Shady Banks	Contributing	1949	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Barrel tile	Casement
BD07031	504216220140	1506 SW 12th Court	Shady Banks	Contributing	1948	Transitional Ranch	Robert Jahelka	Stucco	Flat	Membrane	Double/Single-Hung

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07032	504216220100	1509 SW 12th Court	Shady Banks	Contributing	1948	Transitional Ranch	William T Vaughn	Stucco	Front Gable	Pantile	Double/Single-Hung
BD07033	504216220110	1505 SW 12th Court	Shady Banks	Contributing	1948	Transitional Ranch	William T Vaughn	Stucco	Side Gable	Asphalt shingle	Double/Single-Hung
BD07034	504216220120	1501 SW 12th Court	Shady Banks	Contributing	1958	Transitional Ranch	William T Vaughn	Stucco	Front Gable	asphalt shingle	Double/Single-Hung
BD07035	504216370290	1430 SW 12th Court	Shady Banks	Contributing	1963	Ranch	Unknown	Stucco	Side Gable	Pantile	Awning
BD07036	504216370270	1410 SW 12th Court	Shady Banks	Contributing	1962	Ranch	W.T. Efting	Stucco	Front Gable	Pantile	
BD07037	504216370280	1420 SW 12th Court	Shady Banks	Contributing	1962	Ranch	Arthur Rude	Stucco	Hipped	Barrel tile	Sliding
BD07038	504216370120	1409 SW 12th Court	Shady Banks	Contributing	1962	Ranch	Arthur Rude	Stucco	Hipped	Barrel tile	Fixed
BD07039	504216370130	1415 SW 12th Court	Shady Banks	Contributing	1965	Split Level	John Evans	Stucco	Hipped	Asphalt shingle	Casement
BD07040	504216370260	1400 SW 12th Court	Shady Banks	Contributing	1969	Ranch	Dye and Gomez	Stucco	Side Gable	Barrel tile	Jalousie
BD07041	504216071510	1701 SW 12th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Double/Single-Hung
BD07042	504216071200	1700 SW 12th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Front Gable	Membrane	Double/Single-Hung
BD07043	504216071500	1705 SW 12th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07044	504216071210	1704 SW 12th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Sliding

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07045	504216071490	1709 SW 12th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Casement
BD07046	504216071230	1712 SW 12th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07408	504216071220	1708 SW 12th Court	Shady Banks	Non-Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Awning
BD07047	504216071480	1713 SW 12th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07048	504216071240	1716 SW 12th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07049	504216071470	1717 SW 12th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07409	504216071250	1720 SW 12th Court	Shady Banks	Non-Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Flat	Membrane	Double/Single-Hung
BD07410	504216071460	1721 SW 12th Court	Shady Banks	Non-Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Double/Single-Hung
BD07050	504216071260	1724 SW 12th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Double/Single-Hung
BD07051	504216071450	1725 SW 12th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Cross Gable	Asphalt shingle	Double/Single-Hung
BD07052	504216071270	1728 SW 12th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07053	504216370110	1405 SW 12th Court	Shady Banks	Contributing	1961	Ranch	Arthur Rude	Stucco	Side Gable	Asphalt shingle	Awning
BD07054	504216370190	1400 SW 13th Street	Shady Banks	Contributing	1962	Ranch	Frank Rowland	Stucco	Cross Hipped	Barrel tile	Sliding

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07055	504216370240	1405 SW 13th Street	Shady Banks	Contributing	1961	Transitional Ranch	Ace Gregory	Stucco	Hipped	Barrel tile	Sliding
BD07056	504216370200	1410 SW 13th Street	Shady Banks	Contributing	1962	Ranch	Louis Wolff	Stucco	Side Gable	Asphalt shingle	Casement
BD07057	504216370230	1411 SW 13th Street	Shady Banks	Contributing	1962	Ranch	Ace Gregory	Stucco	Side Gable	Asphalt shingle	Awning
BD07058	504216370210	1420 SW 13th Street	Shady Banks	Contributing	1964	Spanish	Herman Hostettler	Stucco	Side Gable	Pantile	Awning
BD07059	504216370220	1421 SW 13th Street	Shady Banks	Contributing	1963	Ranch	Herman Hostettler	Stucco	Side Gable	Flat tile	Awning
BD07411	504216220221	1505 SW 13th Street	Shady Banks	Non-Contributing	1969	Transitional Ranch	John S. Kantor	Stucco	Hipped	Asphalt shingle	Double/Single-Hung
BD07060	504216220250	1506 SW 13th Street	Shady Banks	Contributing	1959	Transitional Ranch	Arthur Rude	Stucco	Hipped	Flat tile	Awning
BD07061	504216220251	1510 SW 13th Street	Shady Banks	Contributing	1958	Transitional Ranch	William R Smith	Stucco	Hipped	Asphalt shingle	Awning
BD07062	504216220220	1511 SW 13th Street	Shady Banks	Contributing	1958	Transitional Ranch	Charles H. Markel	Stucco	Hipped	Barrel tile	Casement
BD07063	504216220252	1514 SW 13th Street	Shady Banks	Contributing	1959	Transitional Ranch	Arthur Rude	Stucco	Hipped	Barrel tile	Awning
BD07064	504216220210	1515 SW 13th Street	Shady Banks	Contributing	1955	Transitional Ranch	George B. Cunningham	Stucco	Hipped	Asphalt shingle	Jalousie
BD07065	504216220200	1517 SW 13th Street	Shady Banks	Contributing	1957	Contemporary	Charles H. Markel	Stucco	Front Gable	Asphalt shingle	Awning
BD07066	504216220260	1520 SW 13th Street	Shady Banks	Contributing	1957	Transitional Ranch	William R Smith	Stucco	Hipped	Asphalt shingle	Fixed

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07067	504216220270	1524 SW 13th Street	Shady Banks	Contributing	1957	Transitional Ranch	William R Smith	Stucco	Side Gable	Asphalt shingle	Awning
BD07068	504216220190	1525 SW 13th Street	Shady Banks	Contributing	1958	Transitional Ranch	Charles H. Markel	Stucco	Side Gable	Asphalt shingle	Awning
BD07069	504216070150	1600 SW 13th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07412	504216070140	1601 SW 13th Street	Shady Banks	Non-Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07070	504216070160	1604 SW 13th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07071	504216070130	1605 SW 13th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07072	504216070170	1608 SW 13th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Casement
BD07073	504216070120	1609 SW 13th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Casement
BD07074	504216070180	1612 SW 13th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Double/Single-Hung
BD07075	504216070110	1613 SW 13th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Metal	Double/Single-Hung
BD07076	504216070920	1700 SW 13th Street	Shady Banks	Contributing	1951	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Casement
BD07077	504216071380	1701 SW 13th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Cross Gable	Flat tile	Double/Single-Hung
BD07078	504216070930	1704 SW 13th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07079	504216071370	1705 SW 13th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07080	504216070940	1708 SW 13th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07081	504216071360	1709 SW 13th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07082	504216070950	1712 SW 13th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Awning
BD07083	504216071350	1713 SW 13th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07084	504216070960	1716 SW 13th Street	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07413	504216071340	1717 SW 13th Street	Shady Banks	Non-Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Front Gable	Membrane	Fixed
BD07085	504216070970	1720 SW 13th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Casement
BD07086	504216071330	1721 SW 13th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Awning
BD07087	504216070980	1724 SW 13th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Casement
BD07088	504216071320	1725 SW 13th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Casement
BD07089	504216070990	1728 SW 13th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07090	504216071310	1729 SW 13th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07091	504216071000	1732 SW 13th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Casement
BD07092	504216071300	1733 SW 13th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07093	504216071010	1736 SW 13th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07094	504216071020	1740 SW 13th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Casement
BD07095	504216370180	1437 SW 13th Court	Shady Banks	Contributing	1961	Ranch	J. Phillips Jr.	Stucco	Hipped	Asphalt shingle	Awning
BD07096	504216370030	1430 SW 13th Court	Shady Banks	Contributing	1966	Spanish	Herman Hostettler	Stucco	Hipped	Pantile	Awning
BD07097	504216370020	1440 SW 13th Court	Shady Banks	Contributing	1961	Ranch	Louis Wolff	Stucco	Hipped	Pantile	Sliding
	504216370170	1443 SW 13th Court	Shady Banks	Non-Contributing	1973	Contemporary	Philip E. Rickman	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07098	504216370010	1450 SW 13th Court	Shady Banks	Contributing	1963	Ranch	Arthur Rude	Stucco	Side Gable	Pantile	Awning
BD07099	504216370160	1451 SW 13th Court	Shady Banks	Non-Contributing	1965	Ranch	Don Blanchard	Stucco	Hipped	Flat tile	Awning
BD07100	504216220330	1500 SW 13th Court	Shady Banks	Contributing	1948	Minimal Traditional	Unknown	Stucco	Cross Gable	Asphalt shingle	Double/Single-Hung
BD07101	504216220340	1504 SW 13th Court	Shady Banks	Contributing	1957	Contemporary	George C. Hudson	Stucco and Brick	Front Gable	Membrane	Casement
BD07102	504216220310	1507 SW 13th Court	Shady Banks	Contributing	1958	Spanish	Charles H. Markel	Stucco	Hipped	Asphalt shingle	Sliding

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07103	504216220350	1508 SW 13th Court	Shady Banks	Contributing	1957	Contemporary	George C. Hudson	Stucco	Front Gable	Membrane	Jalousie
BD07414	504216220301	1515 SW 13th Court	Shady Banks	Non-Contributing	1962	Transitional Ranch	George P. Cunningham	Stucco	Cross Gable	Asphalt shingle	Awning
BD07104	504216220300	1519 SW 13th Court	Shady Banks	Contributing	1958	Contemporary	George C. Hudson	Stucco	Front Gable	Membrane	Fixed
BD07105	504216220440	1522 SW 13th Court	Shady Banks	Contributing	1955	Transitional Ranch	George Waddey	Wood siding	Side Gable	Barrel tile	Sliding
BD07106	504216220290	1525 SW 13th Court	Shady Banks	Contributing	1957	Contemporary	Charles H. Markel	Stucco	Front Gable	Membrane	Sliding
BD07415	504216070230	1600 SW 13th Court	Shady Banks	Non-Contributing	1957	Contemporary	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07107	504216220280	1531 SW 13th Court	Shady Banks	Contributing	1957	Contemporary	Unknown	Stucco	Front Gable	Membrane	Awning
BD07416	504216070220	1601 SW 13th Court	Shady Banks	Non-Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07108	504216070240	1604 SW 13th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07109	504216070210	1605 SW 13th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07417	504216070250	1608 SW 13th Court	Shady Banks	Non-Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Hipped	Pantile	Double/Single-Hung
BD07110	504216070200	1609 SW 13th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Flat	Membrane	Double/Single-Hung
BD07111	504216070260	1612 SW 13th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Barrel tile	Awning

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07112	504216070730	1700 SW 13th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Awning
BD07113	504216071190	1701 SW 13th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Barrel tile	Double/Single-Hung
BD07114	504216070740	1704 SW 13th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Double/Single-Hung
BD07115	504216071180	1705 SW 13th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Barrel tile	Casement
BD07116	504216070750	1708 SW 13th Court	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Casement
BD07117	504216071170	1709 SW 13th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Casement
BD07118	504216070760	1712 SW 13th Court	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07418	504216071160	1713 SW 13th Court	Shady Banks	Non-Contributing	1952	Transitional Ranch	Unknown	Stucco	Side Gable	Membrane	Fixed
BD07119	504216070770	1716 SW 13th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Casement
BD07120	504216071150	1717 SW 13th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Casement
BD07121	504216070780	1720 SW 13th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Cross Gable	Asphalt shingle	Awning
BD07122	504216071140	1721 SW 13th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Casement
BD07123	504216070790	1724 SW 13th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07124	504216071130	1725 SW 13th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Sliding
BD07125	504216070800	1728 SW 13th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07126	504216071120	1729 SW 13th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07419	504216070810	1732 SW 13th Court	Shady Banks	Non-Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Cross Gable	Metal	Sliding
BD07420	504216071110	1733 SW 13th Court	Shady Banks	Non-Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07127	504216071100	1737 SW 13th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07128	504216070820	1738 SW 13th Court	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07129	504216071090	1741 SW 13th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Casement
BD07130	504216070310	1600 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07131	504216070300	1601 SW 14th Street	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Flat	Membrane	Awning
BD07132	504216070320	1604 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Sliding
BD07133	504216070330	1608 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07134	504216070290	1605 SW 14th Street	Shady Banks	Non-Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07135	504216070280	1609 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Sliding
BD07421	504216070340	1612 SW 14th Street	Shady Banks	Non-Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Sliding
BD07136	504216070270	1613 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07137	504216070390	1700 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Double/Single-Hung
BD07138	504216070910	1701 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Double/Single-Hung
BD07139	504216070400	1704 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07140	504216070900	1705 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07141	504216070410	1708 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07142	504216070890	1709 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Unknown	Unknown	Unknown
BD07143	504216070420	1712 SW 14th Street	Shady Banks	Non-Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07422	504216070880	1713 SW 14th Street	Shady Banks	Non-Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07423	504216070430	1716 SW 14th Street	Shady Banks	Non-Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Ribbon
BD07144	504216070870	1717 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07424	504216070440	1720 SW 14th Street	Shady Banks	Non-Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07145	504216070860	1721 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07146	504216070450	1724 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07425	504216070850	1725 SW 14th Street	Shady Banks	Non-Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Casement
BD07147	504216070460	1728 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07148	504216070840	1729 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07149	504216070470	1732 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Casement
BD07150	504216070830	1733 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07151	504216070480	1736 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Fixed
BD07152	504216070490	1738 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07153	504216070500	1800 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Sliding
BD07154	504216070510	1804 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07155	504216070520	1808 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Sliding

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07156	504216070530	1812 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07157	504216071700	1813 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07158	504216070540	1816 SW 14th Street	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Sliding
BD07159	504216000061	1401 SW 14th Court	Shady Banks	Contributing	1963	Contemporary	William Crawford	Stucco	Hipped	Membrane	Sliding
BD07160	504216220410	1505 SW 14th Court	Shady Banks	Contributing	1957	Transitional Ranch	Charles H. Markel	Stucco	Hipped	Pantile	Sliding
BD07161	504216220400	1509 SW 14th Court	Shady Banks	Contributing	1953	Contemporary	Charles H. Markel	Stucco	Front Gable	Membrane	Double/Single-Hung
BD07162	504216320100	1510 SW 14th Court	Shady Banks	Contributing	1957	Ranch		Stucco	Hipped	Metal	Sliding
BD07163	504216320090	1516 SW 14th Court	Shady Banks	Contributing	1956	Ranch	W.R. Smith	Stucco	Hipped	Asphalt shingle	Sliding
BD07164	504216070380	1601 SW 14th Court	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Sliding
BD07165	504216070370	1605 SW 14th Court	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07166	504216070360	1609 SW 14th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07167	504216070350	1613 SW 14th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Pantile	Double/Single-Hung
BD07168	504216180010	1698 SW 14th Court	Shady Banks	Contributing	1956	Transitional Ranch	Marvin R. Hahn	Stucco	Hipped	Pantile	Awning

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07169	504216070720	1701 SW 14th Court	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Double/Single-Hung
	504216070710	1705 SW 14th Court	Shady Banks	Non-Contributing	2013	Neo-Mediterranean	Robert Jahelka	Stucco	Hipped	Barrel tile	Double/Single-Hung
BD07170	504216070700	1709 SW 14th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07426	504216070690	1713 SW 14th Court	Shady Banks	Non-Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Fixed
BD07171	504216070680	1717 SW 14th Court	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Sliding
BD07427	504216070670	1721 SW 14th Court	Shady Banks	Non-Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Sliding
BD07172	504216070660	1725 SW 14th Court	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07173	504216070650	1729 SW 14th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Unknown
BD07174	504216070640	1733 SW 14th Court	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Sliding
BD07175	504216070630	1737 SW 14th Court	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07176	504216070620	1741 SW 14th Court	Shady Banks	Non-Contributing	1953	Transitional Ranch	Owner	Stucco	Side Gable	Membrane	Sliding
BD07177	504216070610	1801 SW 14th Court	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07178	504216290640	1804 SW 14th Court	Shady Banks	Contributing	1957	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Membrane	Sliding

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07179	504216070600	1805 SW 14th Court	Shady Banks	Contributing	1953		Robert Jahelka	Stucco	Side Gable	Membrane	Unknown
BD07180	504216070590	1809 SW 14th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Sliding
BD07181	504216290630	1810 SW 14th Court	Shady Banks	Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Membrane	Awning
BD07182	504216070580	1813 SW 14th Court	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Flat	Membrane	Casement
BD07183	504216070570	1817 SW 14th Court	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07184	504216290240	1820 SW 14th Court	Shady Banks	Contributing	1952	Transitional Ranch	Lester Avery	Stucco	Side Gable	Membrane	Awning
BD07185	504216290230	1826 SW 14th Court	Shady Banks	Contributing	1953	Transitional Ranch	Lester Avery	Stucco	Side Gable	Membrane	Sliding
BD07428	504216090440	1905 SW 14th Court	Shady Banks	Non-Contributing	1956	Transitional Ranch	Gerard Pitt	Stucco	Cross Gable	Membrane	Double/Single-Hung
BD07186	504216090390	1906 SW 14th Court	Shady Banks	Contributing	1956	Transitional Ranch	Gerard Pitt	Stucco	Side Gable	Membrane	Awning
BD07187	504216090400	1908 SW 14th Court	Shady Banks	Contributing	1956	Transitional Ranch	Gerard Pitt	Stucco	Front Gable	Membrane	Double/Single-Hung
BD07188	504216090430	1909 SW 14th Court	Shady Banks	Contributing	1956	Transitional Ranch	Gerard Pitt	Stucco	Side Gable	Membrane	Casement
BD07189	504216090410	1914 SW 14th Court	Shady Banks	Contributing	1956	Transitional Ranch	Gerard Pitt	Stucco	Front Gable	Membrane	Unknown
BD07190	504216090420	1915 SW 14th Court	Shady Banks	Contributing	1956	Transitional Ranch	Gerard Pitt	Stucco	Front Gable	Membrane	Unknown

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07191	504216370250	1271 SW 14th Avenue	Shady Banks	Contributing	1964	Colonial Revival	Herman Hostettler	Stucco and Brick	Hipped	Flat tile	Awning
BD07429	504216370100	1240 SW 14th Avenue	Shady Banks	Non-Contributing	1964		James Bousfield	Stucco	Complex	Barrel tile	Unknown
BD02111	504216370090	1250 SW 14th Avenue	Shady Banks	Non-Contributing	1962		Unknown	Stucco	Hipped	Barrel tile	Casement
BD07192	504216370080	1260 SW 14th Avenue	Shady Banks	Contributing	1962	Ranch	Paul M. Bradley	Stucco	Hipped	Flat tile	Awning
BD07193	504216370070	1270 SW 14th Avenue	Shady Banks	Contributing	1963	Spanish	Arthur Rude	Stucco	Hipped	Pantile	Awning
BD07431	504216370060	1300 SW 14th Avenue	Shady Banks	Non-Contributing	1963	Spanish	Frank Rowland	Stucco	Hipped	Pantile	Sliding
BD07194	504216370050	1310 SW 14th Avenue	Shady Banks	Contributing	1963	Ranch	Frank Davis	Stucco	Hipped	Metal	Casement
BD07195	504216370040	1320 SW 14th Avenue	Shady Banks	Contributing	1963	Ranch	Arthur Rude	Stucco	Hipped	Flat tile	Awning
BD07196	504216220130	1223 SW 15th Avenue	Shady Banks	Contributing	1951	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Casement
BD07432	504216370150	1212 SW 15th Avenue	Shady Banks	Non-Contributing	1963	Ranch	Arthur Rude	Stucco	Side Gable	Pantile	Casement
	504216220230	1255 SW 15th Avenue	Shady Banks	Non-Contributing	1974	Ranch	Herman Hostettler	Stucco	Side Gable	Barrel tile	Double/Single-Hung
BD07197	504216220240	1301 SW 15th Avenue	Shady Banks	Contributing	1955	Transitional Ranch	George Cunningham	Stucco	Hipped	Asphalt shingle	Casement
BD07198	504216220320	1309 SW 15th Avenue	Shady Banks	Contributing	1955	Transitional Ranch	George Cunningham	Stucco	Hipped	Asphalt shingle	Sliding

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
	504216000050	1400 SW 15th Avenue	Shady Banks	Non-Contributing	2002	Mediterranean	Unknown (Former 1958 House: Charles Markel)	Stucco	Hipped	Barrel tile	Casement
BD07199	504216020060	1401 SW 15th Avenue	Shady Banks	Contributing	1941	Ranch	Unknown	Stucco	Side Gable	Flat tile	Fixed
	504216020070	1403 SW 15th Avenue	Shady Banks	Non-Contributing	N/A		N/A				
	504216020071	1407 SW 15th Avenue	Shady Banks	Non-Contributing	N/A		N/A				
BD07200	504216000052	1410 SW 15th Avenue	Shady Banks	Contributing	1968	Ranch	Herman Hostettler	Stucco	Hipped	Asphalt shingle	Double/Single-Hung
	504216000053	1412 SW 15th Avenue	Shady Banks	Non-Contributing	1977	Contemporary	Fred L Mahoney	Stucco	Flat	Membrane	Fixed
	504216000060	1414 SW 15th Avenue	Shady Banks	Non-Contributing	2000	Neo-Mediterranean	Unkown	Stucco	Hipped	Barrel tile	Double/Single-Hung
BD07201	504216220420	1411 SW 15th Avenue	Shady Banks	Contributing	1957	Transitional Ranch	Charles H. Markel	Stucco	Hipped	Asphalt shingle	Double/Single-Hung
BD07202	504216220430	1415 SW 15th Avenue	Shady Banks	Contributing	1955	Transitional Ranch	George Cunningham	Stucco	Side Gable	Asphalt shingle	Awning
BD07203	504216320110	1425 SW 15th Avenue	Shady Banks	Contributing	1957	Transitional Ranch	Redden	Stucco	Hipped	Pantile	Awning
BD07204	504216160010	1505 SW 15th Avenue	Shady Banks	Contributing	1970	International	Donald Singer	Concrete Block			Unknown
BD07402	504216150010	1500 SW 15th Avenue	Shady Banks	Individual	1970	International	Donald Singer	Concrete	Flat	Membrane	Casement

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07403	504216150070	1509 SW 15th Avenue	Shady Banks	Individual	1976	International	Donald Singer	Concrete	Flat	Membrane	Fixed
	504216150020	1510 SW 15th Avenue	Shady Banks	Non-Contributing	1972	Neo-Mediterranean	Unknown	Stucco	Hipped	Barrel tile	Double/Single-Hung
BD07404	504216150051	1515 SW 15th Avenue	Shady Banks	Individual	1964	Contemporary	Dan Duckham	Concrete	Flat	Membrane	Fixed
	504216150030	1520 SW 15th Avenue	Shady Banks	Non-Contributing	2002	Colonial Revival	Unknown	Stucco	Side Gable	Asphalt shingle	Double/Single-Hung
BD07205	504216150041	1525 SW 15th Avenue	Shady Banks	Contributing	1963	Ranch	Owner	Stucco	Hipped	Barrel tile	Awning
	504216390010	1551 SW 15th Avenue	Shady Banks	Non-Contributing	2006	Contemporary	Unknown	Concrete	Flat	Membrane	Sliding
BD07206	504216330010	1550 SW 15th Avenue	Shady Banks	Contributing	1957	Contemporary	Gamble Pownall & Gilroy	Stucco	Mix	Flat tile	Unknown
	504216330020	1600 SW 15th Avenue	Shady Banks	Non-Contributing	2017		Martin Architect Inc	Stucco	Flat	Membrane	Fixed
BD07433	504216220360	1350 SW 15th Terrace	Shady Banks	Non-Contributing	1958	Contemporary	G.C. Hudson	Stucco	Front Gable	Membrane	Double/Single-Hung
BD07207	504216220361	1354 SW 15th Terrace	Shady Banks	Contributing	1958	Transitional Ranch	Charles H. Markel	Stucco	Side Gable	Barrel tile	Double/Single-Hung
BD07208	504216220370	1358 SW 15th Terrace	Shady Banks	Contributing	1958	Transitional Ranch	Charles H. Markel	Stucco	Side Gable	Barrel tile	Awning
BD07209	504216220460	1359 SW 15th Terrace	Shady Banks	Contributing	1958	Transitional Ranch	Charles H. Markel	Stucco	Side Gable	Flat tile	Awning
BD07210	504216220371	1400 SW 15th Terrace	Shady Banks	Contributing	1958	Transitional Ranch	Charles H. Markel	Stucco	Side Gable	Pantile	Awning

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07211	504216220480	1407 SW 15th Terrace	Shady Banks	Contributing	1957	Transitional Ranch	Charles H. Markel	Stucco	Hipped	Asphalt shingle	Jalousie
	504216220380	1408 SW 15th Terrace	Shady Banks	Non-Contributing	1972	Ranch	Robert F. Dickinson	Stucco	Cross Gable	Asphalt shingle	Sliding
BD07212	504216220390	1416 SW 15th Terrace	Shady Banks	Contributing	1955	Transitional Ranch	George Cunningham	Stucco	Hipped	Asphalt shingle	Jalousie
BD07213	504216220481	1417 SW 15th Terrace	Shady Banks	Contributing	1958	Transitional Ranch	Charles H. Markel	Stucco	Hipped	Pantile	Sliding
BD07214	504216220470	1401 SW 15th Terrace	Shady Banks	Contributing	1958	Transitional Ranch	Charles H. Markel	Stucco	Side Gable	Asphalt shingle	Sliding
BD07215	504216320080	1455 SW 15th Terrace	Shady Banks	Contributing	1960	Ranch	Ray O Peck	Stucco	Hipped	Flat tile	Sliding
BD07216	504216320070	1463 SW 15th Terrace	Shady Banks	Contributing	1965	Ranch	William Presto	Stucco	Cross Gable	Asphalt shingle	Awning
BD07434	504216320060	1467 SW 15th Terrace	Shady Banks	Non-Contributing	1960	Ranch	Paul Revere Working	Stucco and Brick	Cross Gable	Asphalt shingle	Awning
BD07217	504216320050	1471 SW 15th Terrace	Shady Banks	Contributing	1958	Ranch	William Redding	Stucco	Cross Gable	Asphalt shingle	Awning
BD07218	504216320040	1475 SW 15th Terrace	Shady Banks	Contributing	1970	Ranch	William Presto	Stucco	Front Gable	Asphalt shingle	Awning
	504216320030	1479 SW 15th Terrace	Shady Banks	Non-Contributing	1973	Contemporary	William Presto	Stone veneer	Front Gable	Asphalt shingle	Awning
BD07219	504216320020	1483 SW 15th Terrace	Shady Banks	Contributing	1957	Transitional Ranch	Petticord	Stucco	Cross Gable	Asphalt shingle	Awning
BD07220	504216320010	1487 SW 15th Terrace	Shady Banks	Contributing	1956	Transitional Ranch	William Redding	Stucco	Cross Gable	Barrel tile	Sliding

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
	504216150061	1508 SW 15th Terrace	Shady Banks	Non-Contributing	N/A						
BD07435	504216150060	1512 SW 15th Terrace	Shady Banks	Non-Contributing	1953	Transitional Ranch	Unknown	Stucco	Front Gable	Asphalt shingle	Double/Single-Hung
BD07436	504216150050	1516 SW 15th Terrace	Shady Banks	Non-Contributing	1952		Unknown	Unknown	Unknown	Unknown	Unknown
	504216150040	1522 SW 15th Terrace	Shady Banks	Non-Contributing	N/A						
BD07430	504216150042	1530 SW 15th Terrace	Shady Banks	Individual	1975	Contemporary	Donald Singer	Stucco	Flat	Membrane	Unknown
BD07437	504216350230	1605 SW 15th Terrace	Shady Banks	Non-Contributing	1958	Ranch	William Bigoney	Stucco	Hipped	Pantile	Double/Single-Hung
BD07221	504216350240	1609 SW 15th Terrace	Shady Banks	Contributing	1958	Ranch	William Bigoney	Stucco	Cross Gable	Pantile	Double/Single-Hung
	504216350250	1615 SW 15th Terrace	Shady Banks	Non-Contributing	1976	Contemporary	Randall F. Keller	Stucco	Side Gable	Asphalt shingle	Casement
	504216350260	1617 SW 15th Terrace	Shady Banks	Non-Contributing	2016	Neo-Mediterranean	Martin Architect Inc	Stucco	Hipped	Metal	Double/Single-Hung
BD07222	504216350220	1540 SW 16th Street	Shady Banks	Contributing	1958	Ranch	William Bigoney	Stucco	Cross Gable	Barrel tile	Double/Single-Hung
BD07223	504216350210	1600 SW 16th Street	Shady Banks	Contributing	1958	Contemporary	William Bigoney	Stucco	Front Gable	Membrane	Double/Single-Hung
BD07224	504216350200	1610 SW 16th Street	Shady Banks	Contributing	1958	Ranch	William Bigoney	Stucco	Side Gable	Barrel tile	Double/Single-Hung
	504216350080	1700 SW 16th Street	Shady Banks	Non-Contributing	1979	Neo-Spanish Revival	Rodrigo Saavedra	Stucco	Side Gable	Barrel tile	Double/Single-Hung

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
	504216350070	1710 SW 16th Street	Shady Banks	Non-Contributing	2004	Neo-Mediterranean	Joseph E. Phillips	Stucco	Hipped	Metal	Double/Single-Hung
BD07225	504216020150	1900 SW 16th Street	Shady Banks	Contributing	1957	Contemporary	Gerard Pitt	Stucco	Front Gable	Membrane	Fixed
BD07226	504216020160	1906 SW 16th Street	Shady Banks	Contributing	1957	Transitional Ranch	Gerard Pitt	Stucco	Front Gable	Membrane	Double/Single-Hung
BD07227	504216090030	1911 SW 16th Street	Shady Banks	Contributing	1956	Contemporary	Gerard Pitt	Stucco	Front Gable	Membrane	Jalousie
BD07438	504216090020	1907 SW 16th Street	Shady Banks	Non-Contributing	1956	Contemporary	Gerard Pitt	Stone veneer	Front Gable	Membrane	Casement
	504216210040	1998 SW 16th Court	Shady Banks	Non-Contributing	1972		Unknown	Stucco	Hipped	Standing Seam	Double/Single-Hung
BD07228	504216210020	2000 SW 16th Court	Shady Banks	Contributing	1954	Transitional Ranch	Unknown	Unknown	Unknown	Unknown	Unknown
BD07229	504216210031	2002 SW 16th Court	Shady Banks	Contributing	1961	Contemporary	Unknown	Stucco	Front Gable	Barrel tile	Casement
BD07230	504216210080	2010 SW 16th Court	Shady Banks	Contributing	1948	Transitional Ranch	Unknown	Stucco	Side Gable	Membrane	Awning
BD07439	504216210034	2060 SW 16th Court	Shady Banks	Contributing	1964	Ranch		Stucco	Side Gable	Barrel tile	Double/Single-Hung
BD07231	504216210030	2090 Starlight Landing	Shady Banks	Contributing	1940		Unknown	Wood siding	Side Gable	Membrane	Awning
BD07232	504216170010	1426 SW 16th Terrace	Shady Banks	Contributing	1955	Transitional Ranch	Marvin R. Hahn	Stucco	Hipped	Asphalt shingle	Awning
BD07233	504216170110	1427 SW 16th Terrace	Shady Banks	Contributing	1955	Transitional Ranch	Marvin R. Hahn	Stucco	Side Gable	Asphalt shingle	Sliding

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07234	504216170020	1432 SW 16th Terrace	Shady Banks	Contributing	1955	Transitional Ranch	Marvin R. Hahn	Stucco	Side Gable	Asphalt shingle	Sliding
BD07235	504216170120	1433 SW 16th Terrace	Shady Banks	Contributing	1955	Transitional Ranch	Marvin R. Hahn	Stucco	Hipped	Asphalt shingle	Awning
BD07236	504216170030	1436 SW 16th Terrace	Shady Banks	Contributing	1955	Transitional Ranch	Marvin R. Hahn	Stucco	Hipped	Asphalt shingle	Awning
BD07237	504216170130	1437 SW 16th Terrace	Shady Banks	Contributing	1957	Transitional Ranch	Marvin R. Hahn	Stucco	Side Gable	Asphalt shingle	Double/Single-Hung
BD07238	504216170040	1442 SW 16th Terrace	Shady Banks	Contributing	1955	Transitional Ranch	Marvin R. Hahn	Stucco	Side Gable	Asphalt shingle	Double/Single-Hung
BD07440	504216170140	1443 SW 16th Terrace	Shady Banks	Non-Contributing	1956	Transitional Ranch	Marvin R. Hahn	Stucco	Hipped	Asphalt shingle	Double/Single-Hung
BD07239	504216170050	1446 SW 16th Terrace	Shady Banks	Contributing	1955	Transitional Ranch	Marvin R. Hahn	Stucco	Hipped	Flat tile	Sliding
BD07240	504216170150	1447 SW 16th Terrace	Shady Banks	Contributing	1955	Transitional Ranch	Marvin R. Hahn	Stucco	Side Gable	Asphalt shingle	Awning
BD07241	504216170060	1448 SW 16th Terrace	Shady Banks	Contributing	1956	Transitional Ranch	William Redden	Stucco	Side Gable	Membrane	Awning
BD07242	504216170160	1449 SW 16th Terrace	Shady Banks	Contributing	1956	Transitional Ranch	William Redden	Stucco	Side Gable	Asphalt shingle	Sliding
BD07243	504216170070	1454 SW 16th Terrace	Shady Banks	Contributing	1957	Transitional Ranch	William Redden	Stucco	Hipped	Membrane	Double/Single-Hung
BD07244	504216170170	1455 SW 16th Terrace	Shady Banks	Contributing	1957	Transitional Ranch	William Redden	Stucco	Hipped	Barrel tile	Awning
BD07245	504216170180	1459 SW 16th Terrace	Shady Banks	Contributing	1957	Transitional Ranch	William Redden	Stucco	Side Gable	Metal	Sliding

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07246	504216170080	1462 SW 16th Terrace	Shady Banks	Contributing	1957	Transitional Ranch	Marvin R. Hahn	Stucco	Hipped	Asphalt shingle	Double/Single-Hung
BD07441	504216170090	1466 SW 16th Terrace	Shady Banks	Non-Contributing	1956	Transitional Ranch	William Redden	Stucco	Side Gable	Asphalt shingle	Jalousie
BD07442	504216170190	1467 SW 16th Terrace	Shady Banks	Non-Contributing	1956	Transitional Ranch	William Redden	Stucco	Side Gable	Barrel tile	Sliding
BD07247	504216170100	1472 SW 16th Terrace	Shady Banks	Contributing	1957	Transitional Ranch	William Redden	Stucco	Hipped	Asphalt shingle	Sliding
BD07248	504216170200	1473 SW 16th Terrace	Shady Banks	Contributing	1957	Transitional Ranch	William Redden	Stucco	Hipped	Asphalt shingle	Sliding
BD07443	504216020190	1500 SW 17th Street	Shady Banks	Contributing	1954	Ranch	Unknown	Stucco	Hipped	Flat tile	Unknown
BD07249	504216020180	1500 SW 17th Street	Shady Banks	Non-Contributing	1962		Unknown	NA	NA	NA	NA
	504216350300	1513 SW 17th Street	Shady Banks	Non-Contributing	1983	Ranch	Stamas and Associates (Engineer)	Stucco	Hipped	Asphalt shingle	Double/Single-Hung
BD07250	504216350330	1525 SW 17th Street	Shady Banks	Contributing	1968		Unknown	Vertical board	Front Gable	Asphalt shingle	Unknown
	504216350370	1603 SW 17th Street	Shady Banks	Non-Contributing	N/A		Unknown	NA	NA	NA	NA
BD07251	504216350380	1607 SW 17th Street	Shady Banks	Contributing	1960	Transitional Ranch	Arthur Rude	Stucco	Side Gable	Asphalt shingle	Jalousie
BD07252	504216350390	1611 SW 17th Street	Shady Banks	Contributing	1960	Ranch	Unknown	Stucco	Cross Gable	Flat tile	Awning
BD07253	504216350400	1613 SW 17th Street	Shady Banks	Contributing	1966	Contemporary	Frank Rowland	Stucco	Cross Gable	Asphalt shingle	Awning

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07254	504216350410	1701 SW 17th Street	Shady Banks	Contributing	1959	Ranch	Louis Wolff	Stucco	Side Gable	Asphalt shingle	Sliding
	504216350420	1709 SW 17th Street	Shady Banks	Non-Contributing	1973	Ranch	Herman Hostettler	Stucco	Cross Gable	Asphalt shingle	Double/Single-Hung
BD07255	504216350430	1713 SW 17th Street	Shady Banks	Contributing	1960	Transitional Ranch	Frank Rowland	Stucco	Side Gable	Barrel tile	Sliding
BD07444	504216350440	1717 SW 17th Street	Shady Banks	Non-Contributing	1968	Transitional Ranch	Lawrence Browning	Stucco	Flat	Membrane	Double/Single-Hung
	504216020170	1720 SW 17th Street	Shady Banks	Non-Contributing	N/A		N/A	NA	NA	NA	NA
	504216350450	1725 SW 17th Street	Shady Banks	Non-Contributing	1974	Contemporary	Unknown	Stucco	Mix	Membrane	Double/Single-Hung
BD07445	504216070190	1308 SW 17th Avenue	Shady Banks	Non-Contributing	1952	Transitional Ranch	Robert Jahelka	Vinyl siding	Side Gable	Barrel tile	Double/Single-Hung
	504216350190	1600 SW 17th Avenue	Shady Banks	Non-Contributing	1972	Ranch	Herman Hostettler	Stucco	Side Gable	Asphalt shingle	Double/Single-Hung
BD07256	504216350090	1601 SW 17th Avenue	Shady Banks	Contributing	1958	Transitional Ranch	Unknown	Stucco	Side Gable	Asphalt shingle	Casement
BD07257	504216350180	1604 SW 17th Avenue	Shady Banks	Contributing	1970	Ranch	William Presto	Stucco	Cross Gable	Asphalt shingle	Sliding
BD07258	504216350100	1605 SW 17th Avenue	Shady Banks	Contributing	1959	Transitional Ranch	Frank Rowland	Stucco	Cross Gable	Barrel tile	Double/Single-Hung
BD07259	504216350170	1608 SW 17th Avenue	Shady Banks	Contributing	1958	Transitional Ranch	William Bigoney	Stucco	Side Gable	Asphalt shingle	Sliding
	504216350110	1609 SW 17th Avenue	Shady Banks	Non-Contributing	1979	Ranch	Gregory D. Edlund	Stucco	Hipped	Asphalt shingle	Double/Single-Hung

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07260	504216350160	1612 SW 17th Avenue	Shady Banks	Contributing	1968	Contemporary	Fred A. Miller Jr	Stucco	Mix	Asphalt shingle	Unknown
	504216350120	1613 SW 17th Avenue	Shady Banks	Non-Contributing	1979	Contemporary	Unknown	Stone veneer; Vertical board siding	Mix	Asphalt shingle	Fixed
	504216350150	1616 SW 17th Avenue	Shady Banks	Non-Contributing	N/A						
	504216350130	1617 SW 17th Avenue	Shady Banks	Non-Contributing	1974		R. Piniella	Stucco	Mix	Asphalt shingle	Fixed
	504216350140	1620 SW 17th Avenue	Shady Banks	Non-Contributing	1972	Ranch	Herman Hostettler	Stucco	Hipped	Asphalt shingle	Double/Single-Hung
BD07261	504216071280	1218 SW 18th Avenue	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Casement
BD07262	504216071570	1223 SW 18th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Sliding
BD07263	504216071290	1226 SW 18th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07264	504216071580	1227 SW 18th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Metal	Double/Single-Hung
BD07265	504216071590	1231 SW 18th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07266	504216071030	1300 SW 18th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07446	504216071600	1301 SW 18th Avenue	Shady Banks	Non-Contributing	1954	Transitional Ranch	George Moffat	Stucco	Shed	Membrane	Unknown
BD07447	504216071610	1305 SW 18th Avenue	Shady Banks	Non-Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Casement

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07267	504216071620	1309 SW 18th Avenue	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07448	504216071040	1312 SW 18th Avenue	Shady Banks	Non-Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Casement
BD07268	504216071630	1313 SW 18th Avenue	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Fixed
BD07269	504216071050	1316 SW 18th Avenue	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Casement
BD07270	504216071640	1317 SW 18th Avenue	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Barrel tile	Casement
BD07271	504216071060	1320 SW 18th Avenue	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Unknown
BD07272	504216071650	1321 SW 18th Avenue	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07273	504216071070	1324 SW 18th Avenue	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07274	504216071660	1325 SW 18th Avenue	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Awning
BD07275	504216071670	1329 SW 18th Avenue	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07276	504216071680	1333 SW 18th Avenue	Shady Banks	Contributing	1954	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07277	504216071080	1336 SW 18th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07278	504216071690	1337 SW 18th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07279	504216290650	1451 SW 18th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	G. Sherman	Stucco	Side Gable	Metal	Sliding
BD07280	504216290660	1455 SW 18th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Hipped	Barrel tile	Sliding
BD07281	504216290670	1459 SW 18th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Membrane	Sliding
BD07282	504216290680	1463 SW 18th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Membrane	Sliding
BD07283	504216290690	1467 SW 18th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	M.L. Sherman	Stucco	Side Gable	Barrel tile	Double/Single-Hung
BD07449	504216290700	1471 SW 18th Avenue	Shady Banks	Non-Contributing	1953	Transitional Ranch	M.L. Sherman	Stucco and tile veneer	Side Gable	Membrane	Sliding
BD07284	504216200010	1475 SW 18th Avenue	Shady Banks	Contributing	1954	Transitional Ranch	Unknown	Stucco	Side Gable	Asphalt shingle	Sliding
BD07285	504216200020	1479 SW 18th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	M.L. Sherman	Stucco	Side Gable	Membrane	Sliding
BD07286	504216200030	1483 SW 18th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Membrane	Double/Single-Hung
	504216200040	1487 SW 18th Avenue	Shady Banks	Non-Contributing	2018	Neo-Modern	M.T. Sherman	Stucco	Hipped	Metal	Casement
BD07287	504216200050	1491 SW 18th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Asphalt shingle	Double/Single-Hung
BD07288	504216200060	1501 SW 18th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Asphalt shingle	Double/Single-Hung
BD07289	504216200070	1507 SW 18th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Unknown	Stucco	Side Gable	Asphalt shingle	Sliding

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07290	504216290710	1513 SW 18th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Unknown	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07291	504216290720	1519 SW 18th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Unknown	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07450	504216290730	1525 SW 18th Avenue	Shady Banks	Non-Contributing	1953	Transitional Ranch	Unknown	Stucco	Side Gable	Barrel tile	Double/Single-Hung
BD07292	504216290740	1531 SW 18th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Unknown	Stucco	Side Gable	Membrane	Awning
BD07293	504216290750	1537 SW 18th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Unknown	Stucco	Side Gable	Membrane	Awning
BD07294	504216290760	1543 SW 18th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Unknown	Stucco	Side Gable	Flat tile	Awning
BD07295	504216290770	1549 SW 18th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Unknown	Stucco	Side Gable	Asphalt shingle	Sliding
	504216350060	1600 SW 18th Avenue	Shady Banks	Non-Contributing	1972	Ranch	Ronald L Uphoff	Stucco	Cross Gable	Asphalt shingle	Sliding
BD07451	504216350050	1606 SW 18th Avenue	Shady Banks	Non-Contributing	1969	Ranch	Paul M. Bradley	Stucco	Cross Gable	Metal	Sliding
BD07452	504216350040	1612 SW 18th Avenue	Shady Banks	Non-Contributing	1957	Transitional Ranch	William Bigoney	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07453	504216350020	1616 SW 18th Avenue	Shady Banks	Non-Contributing	1958	Transitional Ranch	William Bigoney	Stucco	Side Gable	Asphalt shingle	Double/Single-Hung
BD07454	504216350030	1614 SW 18th Avenue	Shady Banks	Non-Contributing	1958	Transitional Ranch	William Bigoney	Stucco	Side Gable	Metal	Awning
BD07296	504216350021	1624 SW 18th Avenue	Shady Banks	Contributing	1958	Contemporary	William Bigoney	Stucco	Front Gable	Membrane	Double/Single-Hung

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07455	504216290250	1451 SW 18th Terrace	Shady Banks	Non-Contributing	1953	Ranch	Lester Avery	Stucco	Cross Gable	Metal	Double/Single-Hung
BD07456	504216290620	1450 SW 18th Terrace	Shady Banks	Non-Contributing	1953	Ranch	M.T. Sherman	Stucco	Side Gable	Asphalt shingle	Double/Single-Hung
BD07297	504216290610	1454 SW 18th Terrace	Shady Banks	Contributing	1953	Ranch	M.T. Sherman	Stucco	Cross Gable	Asphalt shingle	Double/Single-Hung
BD07457	504216290260	1455 SW 18th Terrace	Shady Banks	Non-Contributing	1953	Transitional Ranch	Lester Avery	Stucco	Mix	Asphalt shingle	Sliding
BD07298	504216290600	1458 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Metal	Sliding
BD07299	504216290270	1459 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	Tony Sherman	Stucco	Side Gable	Membrane	Unknown
BD07458	504216290590	1462 SW 18th Terrace	Shady Banks	Non-Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Asphalt shingle	Double/Single-Hung
BD07300	504216290280	1463 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	Tony Sherman	Stucco	Side Gable	Membrane	Unknown
BD07459	504216290580	1466 SW 18th Terrace	Shady Banks	Non-Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Front Gable	Membrane	Sliding
BD07301	504216290290	1467 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	Tony Sherman	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07302	504216290570	1470 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Membrane	Jalousie
BD07303	504216290300	1471 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	Tony Sherman	Stucco	Side Gable	Membrane	Unknown
BD07304	504216290560	1474 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Metal	Casement

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07305	504216290310	1475 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	Tony Sherman	Stucco	Side Gable	Membrane	Jalousie
BD07306	504216290550	1478 SW 18th Terrace	Shady Banks	Contributing	1957	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Membrane	Unknown
BD07307	504216290320	1479 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	Tony Sherman	Stucco	Side Gable	Membrane	Sliding
BD07308	504216290540	1482 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	Unknown	Wood siding	Side Gable	Asphalt shingle	Double/Single-Hung
BD07309	504216290330	1483 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	Tony Sherman	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07310	504216290530	1486 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07311	504216290340	1487 SW 18th Terrace	Shady Banks	Contributing	1957	Transitional Ranch	Tony Sherman	Stucco	Side Gable	Metal	Sliding
BD07312	504216290520	1490 SW 18th Terrace	Shady Banks	Non-Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Asphalt shingle	Double/Single-Hung
BD07313	504216290350	1491 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	Tony Sherman	Stucco	Side Gable	Asphalt shingle	Sliding
BD07314	504216290510	1500 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Membrane	Awning
BD07315	504216290360	1501 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Barrel tile	Sliding
BD07316	504216290500	1506 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Membrane	Awning
BD07317	504216290370	1507 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Membrane	Sliding

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07318	504216290490	1512 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Asphalt shingle	Awning
BD07319	504216290380	1513 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Membrane	Sliding
BD07320	504216290480	1518 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Barrel tile	Double/Single-Hung
BD07321	504216290390	1519 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Mix	Asphalt shingle	Awning
BD07322	504216290470	1524 SW 18th Terrace	Shady Banks	Contributing	1954	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Membrane	Awning
BD07460	504216290400	1525 SW 18th Terrace	Shady Banks	Non-Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Front Gable	Membrane	Sliding
	504216090070	1526 SW 20th Avenue	Shady Banks	Non-Contributing	2018	Neo-Modern	Unknown	Stucco	Hipped	Asphalt shingle	Double/Single-Hung
BD07323	504216290460	1530 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Membrane	Awning
BD07324	504216290410	1531 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Membrane	Unknown
BD07461	504216290450	1536 SW 18th Terrace	Shady Banks	Non-Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Membrane	Awning
BD07325	504216290420	1537 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Membrane	Unknown
BD07326	504216290440	1542 SW 18th Terrace	Shady Banks	Contributing	1953	Transitional Ranch	M.T. Sherman	Stucco	Side Gable	Membrane	Awning
	504216290430	1543 SW 18th Terrace	Shady Banks	Non-Contributing	2013		M.T. Sherman	Stucco	Hipped	Metal	Double/Single-Hung

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
	504216020141	1600 SW 20th Avenue	Shady Banks	Non-Contributing	1971	Ranch	Hope and Jolley	Stucco	Hipped	Asphalt shingle	Double/Single-Hung
	504216020140	1610 SW 20th Avenue	Shady Banks	Non-Contributing	1971	Ranch	Hope and Jolley	Stucco	Side Gable	Barrel tile	Double/Single-Hung
BD07327	504216080200	1215 SW 19th Avenue	Shady Banks	Contributing	1955	Transitional Ranch	Guy Platt Johnson	Stucco	Front Gable	Membrane	Sliding
BD07462	504216080190	1219 SW 19th Avenue	Shady Banks	Non-Contributing	1954	Transitional Ranch	Guy Platt Johnson	Stucco	Side Gable	Asphalt shingle	Sliding
BD07328	504216080180	1223 SW 19th Avenue	Shady Banks	Contributing	1954	Transitional Ranch	Guy Platt Johnson	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07329	504216080170	1227 SW 19th Avenue	Shady Banks	Contributing	1954	Transitional Ranch	Guy Platt Johnson	Stucco	Front Gable	Barrel tile	Double/Single-Hung
BD07463	504216080160	1231 SW 19th Avenue	Shady Banks	Non-Contributing	1954	Transitional Ranch	Guy Platt Johnson	Stucco	Front Gable	Membrane	Sliding
BD07330	504216080150	1235 SW 19th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Guy Platt Johnson	Stucco	Side Gable	Membrane	Sliding
BD07331	504216080140	1239 SW 19th Avenue	Shady Banks	Contributing	1954	Transitional Ranch	Guy Platt Johnson	Stucco	Side Gable	Membrane	Unknown
BD07464	504216080130	1243 SW 19th Avenue	Shady Banks	Non-Contributing	1954	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07332	504216071810	1300 SW 19th Avenue	Shady Banks	Non-Contributing	1954	Transitional Ranch		Stucco	Side Gable	Membrane	Sliding
BD07333	504216080120	1301 SW 19th Avenue	Shady Banks	Contributing	1954	Transitional Ranch	Guy Platt Johnson	Stucco	Front Gable	Membrane	Sliding
BD07334	504216071800	1304 SW 19th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Double/Single-Hung

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07335	504216080110	1305 SW 19th Avenue	Shady Banks	Contributing	1954	Transitional Ranch	Guy Platt Johnson	Stucco	Side Gable	Membrane	Sliding
BD07336	504216071790	1308 SW 19th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Casement
BD07465	504216080100	1309 SW 19th Avenue	Shady Banks	Non-Contributing	1954	Transitional Ranch	Guy Platt Johnson	Stucco	Side Gable	Pantile	Casement
BD07466	504216071780	1312 SW 19th Avenue	Shady Banks	Non-Contributing	1954	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Casement
	504216080090	1313 SW 19th Avenue	Shady Banks	Non-Contributing	2018	Neo-Modern	Guy Platt Johnson	Stucco	Hipped	Asphalt shingle	Double/Single-Hung
BD07337	504216071770	1316 SW 19th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07467	504216080080	1317 SW 19th Avenue	Shady Banks	Contributing	1954	Transitional Ranch	Guy Platt Johnson	Stucco	Front Gable	Membrane	Double/Single-Hung
BD07338	504216071760	1320 SW 19th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Awning
BD07339	504216080070	1321 SW 19th Avenue	Shady Banks	Contributing	1954	Contemporary	Guy Platt Johnson	Stucco	Front Gable	Asphalt shingle	Fixed
BD07340	504216071750	1324 SW 19th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Sliding
BD07341	504216071740	1328 SW 19th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Sliding
BD07342	504216071730	1332 SW 19th Avenue	Shady Banks	Contributing	1955	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Membrane	Casement
BD07343	504216071720	1336 SW 19th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Flat	Membrane	Casement

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07344	504216071710	1340 SW 19th Avenue	Shady Banks	Contributing	1953	Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Casement
BD07345	504216070550	1400 SW 19th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Asphalt shingle	Casement
BD07346	504216080060	1401 SW 19th Avenue	Shady Banks	Contributing	1954	Transitional Ranch	Guy Platt Johnson	Stucco	Side Gable	Membrane	Casement
BD07347	504216080050	1405 SW 19th Avenue	Shady Banks	Contributing	1954	Transitional Ranch	Guy Platt Johnson	Stucco	Side Gable	Flat tile	Double/Single-Hung
BD07348	504216080040	1409 SW 19th Avenue	Shady Banks	Contributing	1954	Transitional Ranch	Guy Platt Johnson	Stucco	Side Gable	Pantile	Double/Single-Hung
BD07349	504216070560	1410 SW 19th Avenue	Shady Banks	Contributing	1952	Transitional Ranch	Robert Jahelka	Stucco	Side Gable	Flat tile	Awning
BD07350	504216080030	1413 SW 19th Avenue	Shady Banks	Contributing	1955	Transitional Ranch	Gerard Pitt	Stucco	Side Gable	Asphalt shingle	Awning
BD07351	504216080020	1417 SW 19th Avenue	Shady Banks	Contributing	1955	Contemporary	Gerard Pitt	Stucco	Front Gable	Membrane	Double/Single-Hung
BD07352	504216080010	1421 SW 19th Avenue	Shady Banks	Contributing	1954	Contemporary	Gerard Pitt	Stucco	Front Gable	Membrane	Double/Single-Hung
BD07353	504216090450	1425 SW 19th Avenue	Shady Banks	Contributing	1955	Transitional Ranch	Gerard Pitt	Stucco	Side Gable	Membrane	Casement
BD07354	504216090380	1431 SW 19th Avenue	Shady Banks	Contributing	1955	Colonial	Gerard Pitt	Stucco	Side Gable	Asphalt shingle	Awning
BD07355	504216090370	1437 SW 19th Avenue	Shady Banks	Contributing	1955	Transitional Ranch	Gerard Pitt	Stucco	Side Gable	Asphalt shingle	Casement
BD07356	504216090360	1443 SW 19th Avenue	Shady Banks	Contributing	1955	Contemporary	Gerard Pitt	Stucco	Front Gable	Membrane	Sliding

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07357	504216290220	1450 SW 19th Avenue	Shady Banks	Contributing	1954	Transitional Ranch	Unknown	Stucco	Side Gable	Barrel tile	Double/Single-Hung
BD07358	504216290210	1454 SW 19th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Unknown	Stucco	Cross Gable	Asphalt shingle	Awning
BD07468	504216290200	1458 SW 19th Avenue	Shady Banks	Non-Contributing	1953	Transitional Ranch	Lester Avery	Stucco	Cross Gable	Asphalt shingle	Fixed
BD07359	504216290190	1462 SW 19th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Lester Avery	Stucco	Side Gable	Membrane	Awning
BD07360	504216290180	1466 SW 19th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Lester Avery	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07361	504216290170	1470 SW 19th Avenue	Shady Banks	Contributing	1953	Contemporary	Lester Avery	Stucco	Front Gable	Membrane	Double/Single-Hung
BD07469	504216290160	1474 SW 19th Avenue	Shady Banks	Non-Contributing	1953	Transitional Ranch	Lester Avery	Stucco	Side Gable	Asphalt shingle	Sliding
BD07362	504216290150	1478 SW 19th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Lester Avery	Stucco	Side Gable	Membrane	Sliding
BD07363	504216290140	1482 SW 19th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Lester Avery	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07364	504216290130	1486 SW 19th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Tony Sherman	Stucco	Side Gable	Membrane	Sliding
BD07365	504216290120	1490 SW 19th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Tony Sherman	Stucco	Side Gable	Membrane	Sliding
BD07470	504216290110	1500 SW 19th Avenue	Shady Banks	Non-Contributing	1953	Transitional Ranch	Tony Sherman	Stucco	Side Gable	Membrane	Sliding
BD07366	504216090120	1501 SW 19th Avenue	Shady Banks	Contributing	1955	Transitional Ranch	Gerard Pitt	Stucco	Front Gable	Membrane	Sliding

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07367	504216290100	1506 SW 19th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Tony Sherman	Stucco	Side Gable	Asphalt shingle	Sliding
BD07368	504216090130	1511 SW 19th Avenue	Shady Banks	Contributing	1955	Contemporary	Gerard Pitt	Stucco	Front Gable	Membrane	Sliding
BD07369	504216290090	1512 SW 19th Avenue	Shady Banks	Contributing	1955	Transitional Ranch	M. Tony Sherman	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07370	504216090140	1517 SW 19th Avenue	Shady Banks	Contributing	1955	Transitional Ranch	Unknown	Stucco	Side Gable	Flat tile	Sliding
BD07371	504216090150	1523 SW 19th Avenue	Shady Banks	Contributing	1955	Contemporary	Gerard Pitt	Stucco and stone	Mix	Asphalt shingle and Membrane	Sliding
BD07471	504216290080	1524 SW 19th Avenue	Shady Banks	Non-Contributing	1953	Transitional Ranch	Tony Sherman	Stucco	Cross Gable	Barrel tile	Double/Single-Hung
BD07372	504216090160	1529 SW 19th Avenue	Shady Banks	Contributing	1955	Transitional Ranch	Gerard Pitt	Stucco	Side Gable	Asphalt shingle	Awning
BD07373	504216290070	1530 SW 19th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Tony Sherman	Stucco	Side Gable	Membrane	Fixed
BD07374	504216090170	1533 SW 19th Avenue	Shady Banks	Contributing	1955	Contemporary	Gerard Pitt	Stucco	Front Gable	Asphalt shingle	Sliding
BD07375	504216290060	1536 SW 19th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Tony Sherman	Stucco	Side Gable	Membrane	Double/Single-Hung
BD07376	504216090180	1537 SW 19th Avenue	Shady Banks	Contributing	1955	Contemporary	Gerard Pitt	Stucco	Side Gable	Asphalt shingle	Unknown
BD07377	504216290050	1542 SW 19th Avenue	Shady Banks	Contributing	1953	Transitional Ranch	Tony Sherman	Stucco	Side Gable	Membrane	Awning
BD07378	504216090010	1543 SW 19th Avenue	Shady Banks	Contributing	1955	Transitional Ranch	Gerard Pitt	Stucco	Side Gable	Asphalt shingle	Double/Single-Hung

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07379	504216290030	1550 SW 19th Avenue	Shady Banks	Contributing	1967	Contemporary	R.C. Reilly	Stucco and stone veneer	Flat	Membrane	Unknown
BD07380	504216090350	1445 SW 20th Avenue	Shady Banks	Contributing	1956	Contemporary	Gerard Pitt	Stucco	Front Gable	Membrane	Sliding
BD07381	504216090340	1449 SW 20th Avenue	Shady Banks	Contributing	1956	Transitional Ranch	Gerard Pitt	Stucco	Side Gable	Membrane	Sliding
BD07382	504216090330	1453 SW 20th Avenue	Shady Banks	Contributing	1956	Contemporary	Gerard Pitt	Stucco	Front Gable	Membrane	Sliding
BD07383	504216090110	1500 SW 20th Avenue	Shady Banks	Contributing	1956	Transitional Ranch	Gerard Pitt	Stucco	Side Gable	Membrane	Sliding
BD07384	504216090320	1501 SW 20th Avenue	Shady Banks	Contributing	1956	Contemporary	Gerard Pitt	Stucco	Front Gable	Membrane	Double/Single-Hung
BD07385	504216090310	1505 SW 20th Avenue	Shady Banks	Contributing	1956	Transitional Ranch	Gerard Pitt	Stucco	Side Gable	Asphalt shingle	Double/Single-Hung
BD07386	504216090100	1508 SW 20th Avenue	Shady Banks	Contributing	1956	Contemporary	Gerard Pitt	Stucco	Front Gable	Membrane	Sliding
BD07387	504216090300	1509 SW 20th Avenue	Shady Banks	Contributing	1956	Contemporary	Gerard Pitt	Stucco	Front Gable	Membrane	Double/Single-Hung
BD07388	504216090090	1514 SW 20th Avenue	Shady Banks	Contributing	1956	Contemporary	Gerard Pitt	Stucco	Front Gable	Membrane	Casement
BD07389	504216090290	1515 SW 20th Avenue	Shady Banks	Contributing	1956	Contemporary	Gerard Pitt	Stucco	Front Gable	Membrane	Casement
BD07390	504216090080	1520 SW 20th Avenue	Shady Banks	Contributing	1956	Contemporary	Gerard Pitt	Stucco	Front Gable	Membrane	Sliding
BD07391	504216090280	1521 SW 20th Avenue	Shady Banks	Contributing	1956	Transitional Ranch	Gerard Pitt	Stucco	Side Gable	Membrane	Jalousie

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07392	504216090270	1527 SW 20th Avenue	Shady Banks	Contributing	1956	Contemporary	Gerard Pitt	Stucco	Front Gable	Membrane	Double/Single-Hung
BD07393	504216090060	1532 SW 20th Avenue	Shady Banks	Contributing	1956	Contemporary	Gerard Pitt	Stucco	Front Gable	Membrane	Double/Single-Hung
BD07472	504216090260	1533 SW 20th Avenue	Shady Banks	Non-Contributing	1956	Transitional Ranch	Gerard Pitt	Stucco	Front Gable	Membrane	Casement
BD07394	504216090050	1536 SW 20th Avenue	Shady Banks	Contributing	1956	Transitional Ranch	Gerard Pitt	Stucco	Front Gable	Membrane	Casement
BD07395	504216090250	1537 SW 20th Avenue	Shady Banks	Contributing	1956	Transitional Ranch	Gerard Pitt	Stucco	Front Gable	Membrane	Jalousie
BD07396	504216090240	1541 SW 20th Avenue	Shady Banks	Contributing	1956	Contemporary	Gerard Pitt	Stucco	Front Gable	Membrane	Sliding
BD07397	504216090040	1544 SW 20th Avenue	Shady Banks	Contributing	1956	Transitional Ranch	Gerard Pitt	Stucco	Side Gable	Membrane	Sliding
BD07398	504216090230	1545 SW 20th Avenue	Shady Banks	Contributing	1956	Transitional Ranch	Gerard Pitt	Stucco	Side Gable	Asphalt shingle	Sliding
BD07399	504216090220	1549 SW 20th Avenue	Shady Banks	Contributing	1956	Transitional Ranch	Gerard Pitt	Stucco	Front Gable	Membrane	Unknown
BD07400	504216090210	1602 SW 20th Avenue	Shady Banks	Contributing	1957	Contemporary	Unknown	Stucco	Front Gable	Membrane	Jalousie
BD07401	504216090200	1605 SW 20th Avenue	Shady Banks	Contributing	1956	Transitional Ranch	Gerard Pitt	Stucco	Front Gable	Membrane	Sliding
BD07402	504216150010	1500 SW 15th Avenue			1977		Donald Singer	concrete	Flat	membrane	Casement
BD07403	504216150070	1509 SW 15th Avenue			1976			concrete	Flat	membrane	Window Wall

Site ID	Tax Parcel	Address	Historic District	Contributing/ Non-Contributing	Year Built	Style	Architect	Exterior Fabric	Roof Type	Roof Material	Windows
BD07404	504216150051	1515 SW 15th Avenue			1964			concrete	Flat	membrane	Fixed
BD07430	504216150042	1530 SW 15th Avenue			1975			concrete	Flat	membrane	Unknown